




10. SETUP PHOTOS



ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





END OF REPORT