




## 10. SETUP PHOTOS

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






**RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)**







**POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP**





**POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER**





**END OF REPORT**