




## 10. SETUP PHOTOS

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






**RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)**






**RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION**







X-AXIS BACK PHOTO



Y-AXIS FRONT PHOTO



Y-AXIS BACK PHOTO




Z-AXIS FRONT PHOTO






**POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER**








**POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB AND LAPTOP**





**END OF REPORT**