

Report Number: 101930181BOX-001b Issued: 03/26/2015


10.4 Setup Photographs:






30-1000MHz





1-18GHz

Report Number: 101930181BOX-001b Issued: 03/26/2015





18-25GHz Hand scans