

Exhibit: Internal Photos

FCC ID: 2ABFD-9246AE80D86 IC: 1156A-DF9DBB57B1

Report File #: 7169002533-000

© TÜV SÜD Canada Inc. This test report shall not be reproduced except in full, without written approval of TÜV SÜD Canada Inc

| Client | Mircom Group of Companies | |
|-------------|--|--------|
| Product | OpenBAS-HV-WLSTH | |
| Standard(s) | RSS 210 Issue 9:2016, Annex A FCC Part 15 Subpart 15.231:2016 | Canada |




Figure 1 – EUT Internal Photo Front

| Page 2 of 4 | Report Issued: 6/8/2017 | Report File #: 7169002533-000 |
|-------------|-------------------------|-------------------------------|
| | | |

| Client | Mircom Group of Companies | |
|-------------|--|--------|
| Product | OpenBAS-HV-WLSTH | SUD |
| Standard(s) | RSS 210 Issue 9:2016, Annex A FCC Part 15 Subpart 15.231:2016 | Canada |




Figure 2 – EUT Internal Photo Front

Note: In Figure 2 above, the following have been removed: Capacitor "C13", Pushbutton "INC", and the LCD Display

| Client | Mircom Group of Companies | |
|-------------|--|--------|
| Product | OpenBAS-HV-WLSTH | SUD |
| Standard(s) | RSS 210 Issue 9:2016, Annex A FCC Part 15 Subpart 15.231:2016 | Canada |



Figure 3 – EUT Internal Photo Back

| Page 4 of 4 Report Issued: 6/8/2017 Report File #: 7169002533-000 |
|---|
|---|