TEL: 3055315218 FAX: 3056736938

Attestation Letter

October 23, 2015

To:

Federal Communications Commission
Office of Engineering and Technology Laboratory Division
7435 Oakland Mills Rd
Columbia MD 21046-1609

Phone: +1-301-362-3000 Fax: +1-301-362-3290

Dear Sir or Madam:

The RF chip, model MTK6735, installed in FCC ID: 2ABOSGCSKY50LM, supports LTE B41 functions. For use in the US this chip will not support/enable the LTE B41 function. The LTE B41 function has been shielded by the manufacturer using the software.

Best Regards,

Roberto Conrado

PD