



POSITION - LEFT CABLE




Label to be wrapped around the left cable, see packaging 3D for exact positioning.
Label should be attached to the cable using the small centre tab only, the two larger sections should then be joined neatly together so the glue sides match and align exactly.

LABEL ADHESIVE



Adhesive should only be added to the two rectangle parts so they can be fixed together, no adhesive should be put on the centre joining part that wraps around the cable, see blue area above.



do not print

Perforate centre of label join to ensure label can be removed from cable without damaging the cable.



print this version

Material 3M 7818	FINISH CMYK as above			COPYRIGHT © 2019	
				DRAWN BY KH	DATE 04/02/2019
Bowers & Wilkins	DIMENSIONS IN mm	SCALE	ISS	PART NUMBER	
	TOLERANCES 0. ± 0.5 0.0 ± 0.3 0.00 ± 0.1		USED ON TITLE:- DRAFT GLOBAL - PI3 Cable Rating Label	SAP ART NUMBER	