


# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

**(Internal)**




# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)



# INTERTEK TESTING SERVICE

Report No.: HK20070829

## Equipment Photographs

(Internal)

