

Photos

Subject: SFFR6UH2 External Photographs

Date: 31st August 2021

Revision: 1.00

Forward

This document contains photographs with respect to the filing of permissive changes to the product SFFR6UH2 product:

FCC ID: 2ADAKSFFR6UH2

IC: 9487A-SFFR6UH2

This document includes three sets of changes, these are defined as:

- Single External RF Port and Internal Duplexer (Configuration 1)
- Two External RF Ports and No Internal Duplexer (Configuration 2)
- Two External RF Ports and an Internal Duplexer (Configuration 3)

The first four photographs of the document are photographs from the original.

The photographs following the first four photographs relate to the changes.

31st August 2021



Photo 1 – From Original Filing (Duplexer Bypass Module was removed).





Photo 2 – From Original Filing





Photo 3 - Original Filing





Photo 4 - Original Filing

(Duplexer Bypass Module was removed).





Single External RF Port and Internal Duplexer (Configuration 1)

Note: The external appearance is the same to the original filing, the only change is from Duplexer Bypass Module to a Duplexer Module. The Duplexer Module has an internal duplexer. The module differs from the Duplexer Bypass Module in that the module has a faceplate which is fixed with screws for servicing access to the internal duplexer part.

Photo 5 Single External RF Port and Internal Duplexer (Configuration 1) with Duplexer Module fitted





Date:

31st August 2021

Two External RF Ports and No Internal Duplexer (Configuration 2)

Note: The external appearance is similar to the original filing. The main change is the two ports on the front panel. The internals of the Duplexer Bypass Unit have changed.

Photo 6 Two External RF Ports and No Internal Duplexer (Configuration 2) with Duplexer Bypass Module Fitted.





Two External RF Ports and No Internal Duplexer (Configuration 2)

Note: The external appearance is similar to the original filing. The only change the two RF ports on the front panel. The internals of the Duplexer Bypass Module are different to the original filing.

Photo 7 Two External RF Ports and No Internal Duplexer (Configuration 2) – Front Panel with Two external RF Ports.





Two External RF Ports and an Internal Duplexer (Configuration 3)

Note: The external appearance is similar to the original filing. The only two changes.

- Two RF Ports on the front panel
- The fitting of Duplexer Module

The two RF Ports on the front panel change is the same that is illustrated in: *Photo 7 Two External RF Ports and No Internal Duplexer (Configuration 2) – Front Panel with Two external RF Ports.*

The fitting of Duplexer Module is the same change that is illustrated in: Photo 5 Single External RF Port and Internal Duplexer (Configuration 1) with Duplexer Module fitted

.