

US Tech Test Report:
Report Number:
Customer:
FCC ID:
IC:
Issue Date:
Model:

FCC Part 15.249/RSS 210
14-0273
Acuity Brands Lighting
2ADCB-DTL02
6715C-DTL02
November 7, 2014
DTL02

INTERNAL PHOTOGRAPHS



Figure 1. EUT with Top External Case Removed

US Tech Test Report:
Report Number:
Customer:
FCC ID:
IC:
Issue Date:
Model:

FCC Part 15.249/RSS 210
14-0273
Acuity Brands Lighting
2ADCB-DTL02
6715C-DTL02
November 7, 2014
DTL02



Figure 2. EUT with Top External Case and Buttons Removed

US Tech Test Report:
Report Number:
Customer:
FCC ID:
IC:
Issue Date:
Model:

FCC Part 15.249/RSS 210
14-0273
Acuity Brands Lighting
2ADCB-DTL02
6715C-DTL02
November 7, 2014
DTL02




Figure 3. Back of EUT with External Cases Removed

US Tech Test Report:
Report Number:
Customer:
FCC ID:
IC:
Issue Date:
Model:

FCC Part 15.249/RSS 210
14-0273
Acuity Brands Lighting
2ADCB-DTL02
6715C-DTL02
November 7, 2014
DTL02



Figure4. Back of EUT with Shielding Removed