



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:29:16

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:29:27

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:29:44

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:29:55

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:30:09

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:30:20

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:31:03

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:31:13

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:31:31

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:31:41

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:31:56

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:32:07

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:33:25

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:33:36

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:33:51

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:34:02

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:34:19

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:34:33

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:35:12

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:35:23

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:35:41

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:35:52

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:36:07

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:36:18

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:37:08

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:37:19

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:37:36

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:37:47

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:38:05

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:38:16

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:39:01

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:39:12

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:39:30

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:39:41

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:39:59

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:40:10

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:40:33

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:40:44

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:40:58

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:41:09

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:41:23

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:41:33

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:42:38

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:42:49

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:43:03

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:43:14

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:43:28

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:43:39

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:44:17

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:44:28

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:44:43

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:44:54

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:45:08

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:45:19

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:46:01

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:46:12

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:46:31

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:46:42

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:46:57

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:47:08

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:47:49

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:48:01

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:48:18

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:48:29

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:48:47

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:48:58

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:50:06

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:50:17

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:50:38

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:50:48

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:51:09

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:51:18

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:25:57

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:26:07

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:26:20

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:26:30

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:26:45

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:26:55

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:28:09

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:28:19

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:28:35

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:28:45

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:29:00

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:29:10

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:31:28

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:31:41

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:31:54

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:32:04

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:32:16

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:32:26

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:33:37

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:33:47

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:33:59

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:34:10

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:34:25

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:34:35

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:51:41

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:51:51

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:52:08

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:52:18

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:52:32

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:52:42

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:53:20

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:53:30

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:53:45

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:53:55

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:54:09

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:54:19

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:55:10

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:55:20

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:55:40

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:55:50

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:56:07

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:56:17

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:56:59

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:57:09

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:57:27

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:57:37

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:57:54

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 31.JUL.2022 14:58:04

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:34:54

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:35:04

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:35:19

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:35:29

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:35:45

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:35:55

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:36:46

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:36:56

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:37:12

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:37:22

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:37:37

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:37:47

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:38:43

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:38:53

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:39:08

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:39:19

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:39:31

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:39:41

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:40:51

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:41:02

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:41:14

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:41:24

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:41:40

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:41:50

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:42:09

Band 13_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:42:19

Band 13_5 MHz_Low_QPSK_RB25#0_3(763MHz-775MHz)




Date: 16.AUG.2022 01:42:29

Band 13_5 MHz_Low_QPSK_RB25#0_4(793MHz-806MHz)




Date: 16.AUG.2022 01:42:42

Band 13_5 MHz_Low_QPSK_RB25#0_5(1.559GHz-1.61GHz)




Date: 28.JUL.2022 15:23:37

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:43:04

Band 13_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:43:14

Band 13_5 MHz_Middle_QPSK_RB25#0_3(763MHz-775MHz)




Date: 16.AUG.2022 01:43:27

Band 13_5 MHz_Middle_QPSK_RB25#0_4(793MHz-806MHz)




Date: 16.AUG.2022 01:43:40

Band 13_5 MHz_Middle_QPSK_RB25#0_5(1.5590GHz-1.61GHz)




Date: 16.AUG.2022 01:43:50

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:44:02

Band 13_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:44:13

Band 13_5 MHz_High_QPSK_RB25#0_3(763MHz-775MHz)




Date: 16.AUG.2022 01:44:26

Band 13_5 MHz_High_QPSK_RB25#0_4(793MHz-806MHz)




Date: 16.AUG.2022 01:44:39

Band 13_5 MHz_High_QPSK_RB25#0_5(1.559GHz-1.61GHz)




Date: 16.AUG.2022 01:44:49

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2022 01:45:52

Band 13_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2022 01:46:02

Band 13_10 MHz_Middle_QPSK_RB50#0_3(763MHz-775MHz)




Date: 16.AUG.2022 01:46:15

Band 13_10 MHz_Middle_QPSK_RB50#0_4(793MHz-806MHz)




Date: 16.AUG.2022 01:46:28

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1.5590GHz-1.61GHz)




Date: 28.JUL.2022 15:29:01

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:56:43

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:56:54

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:57:12

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:57:23

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:57:40

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:57:51

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:58:30

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:58:41

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:58:56

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:59:07

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:59:25

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 18:59:36

Band 25_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:58:23

Band 25_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:58:33

Band 25_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:58:46

Band 25_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:58:56

Band 25_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:59:09

Band 25_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 14:59:19

Band 25_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 14:59:57

Band 25_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:00:07

Band 25_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:00:23

Band 25_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:00:33

Band 25_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:00:50

Band 25_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:00:59

Band 25_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:01:39

Band 25_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:01:48

Band 25_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:02:02

Band 25_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:02:12

Band 25_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:02:26

Band 25_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:02:36

Band 25_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:04:16

Band 25_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:04:26

Band 25_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:04:44

Band 25_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:04:54

Band 25_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:05:12

Band 25_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:05:21

Band 25_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:06:21

Band 25_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:06:31

Band 25_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:06:48

Band 25_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:06:58

Band 25_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:07:14

Band 25_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:07:24

Band 25_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:08:06

Band 25_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:08:16

Band 25_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:08:34

Band 25_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2022 18:22:23

Band 25_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:09:13

Band 25_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:09:23

Band 26_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:34:00

Band 26_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:34:10

Band 26_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:34:24

Band 26_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:34:35

Band 26_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:34:49

Band 26_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:35:00

Band 26_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:35:17

Band 26_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:35:28

Band 26_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:35:42

Band 26_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:35:53

Band 26_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:36:10

Band 26_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:36:24

Band 26_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:36:45

Band 26_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:36:56

Band 26_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:37:10

Band 26_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:37:21

Band 26_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:37:39

Band 26_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:37:50

Band 26_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.JUL.2022 16:38:11

Band 26_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.JUL.2022 16:38:22

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:31:27

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:31:38

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:31:53

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:32:04

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:32:18

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:32:29

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:33:11

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:33:22

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:33:37

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:33:48

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:34:03

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:34:14

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:34:59

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:35:10

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:35:28

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:35:39

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:35:59

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:36:10

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:36:52

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:37:03

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:37:21

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:37:32

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.JUL.2022 18:37:53

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.JUL.2022 18:38:04

Band 66_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:09:43

Band 66_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:09:54

Band 66_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:10:11

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:10:22

Band 66_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:10:36

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:10:47

Band 66_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:11:39

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:11:50

Band 66_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:12:04

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:12:15

Band 66_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:12:32

Band 66_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:12:43

Band 66_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:13:26

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:13:37

Band 66_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:13:55

Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:14:06

Band 66_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:14:23

Band 66_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:14:34

Band 66_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:15:21

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:15:32

Band 66_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:15:51

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:16:02

Band 66_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:16:17

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:16:31

Band 66_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:17:19

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:17:30

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:17:51

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:18:02

Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:18:20

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:18:31

Band 66_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:19:20

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:19:30

Band 66_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:19:49

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:20:00

Band 66_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.JUL.2022 15:20:18

Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 31.JUL.2022 15:20:29

Band 71_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 18:59:53

Band 71_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:00:04

Band 71_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:00:19

Band 71_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:00:30

Band 71_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:00:47

Band 71_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:00:58

Band 71_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:02:12

Band 71_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:02:23

Band 71_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:02:41

Band 71_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:02:55

Band 71_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:03:13

Band 71_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:03:24

Band 71_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:04:13

Band 71_15 MHz_Low_QPSK_RB75#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:04:24

Band 71_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:04:41

Band 71_15 MHz_Middle_QPSK_RB75#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:04:52

Band 71_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:05:10

Band 71_15 MHz_High_QPSK_RB75#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:05:20

Band 71_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:06:29

Band 71_20 MHz_Low_QPSK_RB100#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:06:40

Band 71_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.JUL.2022 19:06:58

Band 71_20 MHz_Middle_QPSK_RB100#0_2(1GHz-10GHz)




Date: 29.JUL.2022 19:07:09

Band 71_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 29.JUL.2022 19:07:27

Band 71_20 MHz_High_QPSK_RB100#0_2(1GHz-10GHz)



Date: 29.JUL.2022 19:07:41