

11.Radiated Measurement Setup Configuration





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan :+886-2-7737-3000 Telephone Facsimile (FAX) :+886-3-583-7948



| Test report No. | : 4788494033-US-R0-V0 |
|-----------------|-----------------------|
| Page | : 48 of 50 |
| Issued date | : June 5, 2018 |
| FCC ID | : 2ADKC-TVS |

Above 1 GHz



Underwriters Laboratories Taiwan Co., Ltd. Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948 Doc No: 17-EM-F0877 / 1.0



12.Conducted Emission Measurement Setup Configurations



Underwriters Laboratories Taiwan Co., Ltd. Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948 Doc No: 17-EM-F0877 / 1.0



| Test report No. | : 4788494033-US-R0-V0 |
|-----------------|-----------------------|
| Page | : 50 of 50 |
| Issued date | : June 5, 2018 |
| FCC ID | : 2ADKC-TVS |



Underwriters Laboratories Taiwan Co., Ltd. Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948 Doc No: 17-EM-F0877 / 1.0