



ESSYS Co., Ltd.

55, Gaetbeol-ro, Yeonsu-gu, Incheon,
Republic of Korea
AUG 16, 2023

Federal Communications
Commission Authorization and
Evaluation Division 7435 Oakland
Mills Road,
Columbia, MD 21046

Certification and Engineering Bureau
ISED Canada
3701 Carling Ave., Bldg. 94, Ottawa,
ON, K2H 8S2

**Class II Permissive Change for
FCC ID: 2ADQJ-YSP88459SM / IC : 28512-YSP88459SM**

We, ESSYS Co., Ltd., as a manufacturer of following models hereby declare that they have the following differences in supported features.

Model : BWR-YSP88459-SMA-LGA

The reason for this update is the dualization of the component vendor. Consequently, a change has been implemented by amending the SAW filter within the Bluetooth pathway. new component has similar RF characteristics with previous component. All of other components are unchanged.

For details, please refer to Annex.

Sincerely Yours,

A handwritten signature in black ink, appearing to read "Sung Hoon Kim".


Name : Sung Hoon Kim _____
Title : Research Engineer
Company : ESSYS Co., Ltd.

Variant Difference

Basic Model : BWR-YSP88459-SMA




Variant Model : BWR-YSP88459-SMA-LGA



#. Filter change of only Bluetooth path

Bluetooth

Basic Model : BWR-YSP88459-SMA



Bluetooth

Variant Model : BWR-YSP88459-SMA-LGA

