## **Correspondence by Project**

## **Project Number:**

-558605972

| Correspondence Number | Memo  |
|-----------------------|---|
| 2ADT3-BA1000-1        | an FCC ID sample label did not have an FCC ID on it. Please provide a new sample. Response: The FCC ID Label has been revised to show the FCC ID on it. 2) The letter of authority and anti-drug abuse letter has an address that does not match the Grantee address of record. Please provide a corrected letter. Response: The address has been changed on the FCC database for the grantee code. 3) There was not a TCB submittal attestation letter submitted. Please provide this attestation letter. Response: The TCB submittal attestation has been signed and uploaded. 4) Please provide documentation showing RF exposure compliance. Response: The RF exposure compliance document has been uploaded. 5) Please show data showing compliance to the 15.31(e) requirements. Response: The 15.31(e) requirements has been uploaded. 6) Please indicate the type of modulation employed by the device. Response: The modulation is QFSK. 7) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block. Response: The block diagram has been revised. 8) An operational description for the radio portion was only provided. Please provide an operational description of the device as well. Response: A supplemental Operational Description has been uploaded. 9) Please provide documentation that the device meets the |

1 of 2 2/23/2015 11:32 AM

FHSS requirements. Response: Please see the FHSS requirements documents from the manufacturer 10) The user manual does not have any RF exposure statement and an incorrect FCC ID. Please provide a corrected user manual. Response: The Owner's manual has been revised to show the RF exposure statement. 11) The user manual has a watermark stating confidentiality, however the manual cannot be held confidential. Please confirm that the Grantee is aware that this will not be held confidential. Response: The user manual will not be confidential.

2 of 2 2/23/2015 11:32 AM