



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:13:29

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:48:09

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:48:12

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:49:20

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:49:52

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:50:03

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:50:21

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:51:04

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:50:45

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:51:31

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:51:09

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:52:05

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:51:34

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:52:53

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 12:52:01


### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 10:53:21




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:52:29

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:54:06

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:52:54

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:54:50

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:53:22

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:55:15

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:53:46

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:55:52

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:54:16

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:56:57

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:54:44

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 10:59:38

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:55:12

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:00:04

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 12:55:42


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 11:01:11




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:56:10

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:01:45

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 12:56:38

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:02:10

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:00:35

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:03:14

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:03:16

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:04:14

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:04:44

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:05:09

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:05:13

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:06:06

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:05:40

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:06:30

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:06:04


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 11:06:50




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:06:30

### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:07:17

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:06:57

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:07:46

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:07:21

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:08:11

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:07:46

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:09:05

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:08:11

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:09:30

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:08:35

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:09:55

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:09:02

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:10:48

### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:09:30


### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 11:11:09




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:09:58

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:11:31

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:10:28

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:12:23

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:10:56

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:12:56

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:11:21

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:13:22

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:11:47

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:16:31

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:12:15

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:17:00

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:12:42

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:17:28

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:13:11


### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 7.DEC.2022 11:18:14




### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:13:38

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:18:36

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:14:06

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:19:08

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:14:32

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:19:53

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:14:57

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:20:27

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:15:22

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:20:53

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:15:51

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:21:31

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:16:20

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 11:21:55

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:16:45


### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 7.DEC.2022 11:22:25




### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:18:59

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:24:03

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:20:02

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:24:30

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:21:45

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:24:51

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:22:13

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:26:10

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:22:45

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:26:36

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:23:10

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:27:51

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:23:38

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:28:17

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:24:10


### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 11:28:40




### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:24:34

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:29:25

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:25:03

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:30:21

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:25:31

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:30:59

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:25:59

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:31:26

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:26:28

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:32:11

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:26:56

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:32:38

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:27:24

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:34:00

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 24.NOV.2022 13:27:50


### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 7.DEC.2022 11:34:29




### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:28:15

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:34:54

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.NOV.2022 13:28:40

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 7.DEC.2022 11:35:38

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:46:47

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:29:51

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:46:17

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:31:23

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:45:50

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:32:22

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:47:28

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:32:51

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:48:12

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:33:51

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 7.DEC.2022 11:48:51


### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 25.NOV.2022 09:34:16




### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:49:51

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:34:43

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:50:12

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:35:12

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:50:36

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:35:40

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 09:36:01

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:36:12

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 09:36:27

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:36:38

### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 09:36:53

### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:37:04

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:53:29

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:37:38

### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 7.DEC.2022 11:55:19


### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)



Date: 25.NOV.2022 09:49:17




### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:56:56

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:58:54

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:57:36

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:59:21

### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:58:00

### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 09:59:46

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 7.DEC.2022 11:58:30

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:00:57

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:01:17

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:01:28

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:01:45

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:01:56

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:02:11

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:02:22

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 25.NOV.2022 10:02:38


### Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 25.NOV.2022 10:02:49




### Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:03:04

### Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:03:15

### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:03:30

### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:03:41

### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:03:58

### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:04:09

### Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:04:23

### Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:04:34

### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:04:49

### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:04:59

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:05:54

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:06:05

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 10:06:20

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 25.NOV.2022 10:06:34

### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 25.NOV.2022 10:06:49


### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 25.NOV.2022 10:07:00




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:32:53

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 13:14:37

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:33:20

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 13:16:00

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:33:44

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 7.DEC.2022 13:16:52

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:34:13

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:34:24

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:34:38

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:34:49

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:35:02

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:35:13

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:35:32

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:35:43

### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 25.NOV.2022 11:36:00


### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 7.DEC.2022 13:19:31




### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:36:28

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:36:39

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:36:59

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:37:09

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:37:23

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:37:34

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 11:37:49

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 25.NOV.2022 11:37:59

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:08:21


### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.55GHz)



Date: 22.DEC.2022 07:30:02




Date: 25.NOV.2022 13:08:45




Date: 22.DEC.2022 07:30:30

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:09:12

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:31:25

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:16:28

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:31:57






Date: 25.NOV.2022 13:16:52




Date: 22.DEC.2022 07:32:42

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:17:20

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:33:13

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:18:20

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:34:09

### Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:18:45

### Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:34:39

### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:19:09

### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:35:43

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:20:09

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:36:12

### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 25.NOV.2022 13:20:34

### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.55GHz)




Date: 22.DEC.2022 07:36:49

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 25.NOV.2022 13:20:59

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.55GHz)



Date: 22.DEC.2022 07:37:41