



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:28:11

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:28:22

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:28:35

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:28:45

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:29:02

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:29:13

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:29:50

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:30:01

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:30:14

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:30:25

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:30:38

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:30:49

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:31:27

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:31:37

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:31:52


### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 11:32:05




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:32:18

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:32:29

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:33:15

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:33:26

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:33:43

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:33:54

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:34:10

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:34:21

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:35:07

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:35:18

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:35:32

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:35:43

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:36:00

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:36:11

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:37:07


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 11:37:18




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:37:35

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:37:46

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:38:00

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:38:11

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:38:30

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:38:41

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:38:57

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:39:08

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:39:24

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:39:35

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:40:20

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:40:31

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:40:47

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:40:58

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:41:14


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 11:41:25




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:42:13

### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:42:24

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:42:40

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:42:51

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:43:04

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:43:15

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:43:53

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:44:04

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:44:17

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:44:28

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:44:42

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:44:53

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:45:34

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:45:45

### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:45:59


### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 11:46:10




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:46:24

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:46:35

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:47:13

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:47:24

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:47:38

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:47:49

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:48:06

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:48:17

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:48:33

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:48:44

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:48:57

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:49:08

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:49:24

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:49:35

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:50:13


### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 21.DEC.2022 11:50:25




### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:50:38

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:50:49

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:51:02

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:51:13

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:51:52

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:52:03

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:52:17

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:52:27

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:52:42

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:52:53

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:53:38

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:53:50

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:54:07

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 21.DEC.2022 11:54:18

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:54:32


### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 21.DEC.2022 11:54:43




### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:54:58

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:55:09

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:55:25

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:55:36

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:55:53

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:56:03

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:56:41

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:56:52

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:57:08

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:57:19

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:57:32

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:57:42

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:58:20

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:58:31

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 11:58:47


### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 11:58:58




### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 11:59:14

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 11:59:25

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:00:10

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:00:21

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:00:38

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:00:49

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:01:05

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:01:16

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:02:10

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:02:20

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:02:37

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:02:48

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:03:02

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:03:13

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 12:10:01


### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 21.DEC.2022 12:10:12




### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:10:26

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:10:37

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 12:10:54

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.DEC.2022 12:11:05

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:10:44

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:10:55

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:11:11

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:11:22

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:11:35

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:11:46

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:12:31

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:12:42

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:12:55

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:13:09

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 15:13:22


### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 21.DEC.2022 15:13:33




### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:14:22

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:14:33

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:14:49

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:15:00

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:15:13

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:15:24

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:16:17

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:16:28

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 15:16:42


### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 21.DEC.2022 15:16:52




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:17:35

### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:17:46

### Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 21.DEC.2022 15:17:59


### Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 21.DEC.2022 15:18:10




### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:18:29

### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:18:40

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:19:24

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:19:35

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:19:48

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:19:59

### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.DEC.2022 15:20:17

### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.DEC.2022 15:20:28

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:31:35

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:31:46

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:31:59

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:32:10

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:32:23

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:32:34

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 28.DEC.2022 23:33:30


### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 28.DEC.2022 23:33:41




Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:33:58

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:34:12

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:34:28

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:34:39

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:35:17

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:35:28

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:35:42

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:35:53

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:36:06

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:36:17

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:36:56

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:37:07

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 28.DEC.2022 23:37:23

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 28.DEC.2022 23:37:34

### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 28.DEC.2022 23:37:48


### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 28.DEC.2022 23:37:59




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:23:44

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:23:55

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:24:11

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:24:22

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:24:35

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:24:46

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:25:31

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:25:42

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:25:56

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:26:07

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:26:20

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:26:31

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:27:20

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:27:31

### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 26.DEC.2022 10:27:45


### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 26.DEC.2022 10:27:56




### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:28:13

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:28:24

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:29:09

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:29:20

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:29:38

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:29:48

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:30:03

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 10:30:13

Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 09:59:23

Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:50:56

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:00:35

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 26.DEC.2022 14:52:49

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:01:03

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:53:52

Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 26.DEC.2022 10:01:32


Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.55GHz)



Date: 26.DEC.2022 14:54:54




Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:01:56

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:55:38

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:02:23

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:56:20

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:02:55

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:57:11

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:03:20

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:58:01

Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:03:48

Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 14:58:42

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:04:14

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 15:01:16

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 26.DEC.2022 10:04:40

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.55GHz)




Date: 26.DEC.2022 15:04:02

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 26.DEC.2022 10:05:05

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.55GHz)



Date: 26.DEC.2022 15:05:07