



n77\_3\_30MHz\_30kHz\_3715MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 10:16:07

n77\_3\_30MHz\_30kHz\_3715MHz\_DFT-s-OFDM  
QPSK\_RB75@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 13:53:32

n77\_3\_30MHz\_30kHz\_3965MHz\_DFT-s-OFDM  
QPSK\_RB1@77




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 15:52:45

n77\_3\_30MHz\_30kHz\_3965MHz\_DFT-s-OFDM  
QPSK\_RB75@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 15:53:14

n77\_3\_40MHz\_30kHz\_3720MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 15:57:06

n77\_3\_40MHz\_30kHz\_3720MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 10:49:54

n77\_3\_40MHz\_30kHz\_3960MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 15:59:41

n77\_3\_40MHz\_30kHz\_3960MHz\_DFT-s-OFDM  
QPSK\_RB1@105




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 15:57:41

n77\_3\_50MHz\_30kHz\_3725MHz\_DFT-s-OFDM  
QPSK\_RB128@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:35:08

n77\_3\_50MHz\_30kHz\_3725MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:00:17

n77\_3\_50MHz\_30kHz\_3955MHz\_DFT-s-OFDM  
QPSK\_RB128@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:02:54

n77\_3\_50MHz\_30kHz\_3955MHz\_DFT-s-OFDM  
QPSK\_RB1@132




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:02:23

n77\_3\_60MHz\_30kHz\_3730MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:05:42

n77\_3\_60MHz\_30kHz\_3730MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:05:12

n77\_3\_60MHz\_30kHz\_3950MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:07:30

n77\_3\_60MHz\_30kHz\_3950MHz\_DFT-s-OFDM  
QPSK\_RB1@161




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:06:58

n77\_3\_70MHz\_30kHz\_3735MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:12:23

n77\_3\_70MHz\_30kHz\_3735MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:08:40

n77\_3\_70MHz\_30kHz\_3945MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:14:08

n77\_3\_70MHz\_30kHz\_3945MHz\_DFT-s-OFDM  
QPSK\_RB1@188




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:12:57

n77\_3\_80MHz\_30kHz\_3740MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 13:54:41

n77\_3\_80MHz\_30kHz\_3740MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:15:16

n77\_3\_80MHz\_30kHz\_3940MHz\_DFT-s-OFDM  
QPSK\_RB1@216




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:16:17

n77\_3\_80MHz\_30kHz\_3940MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:16:47

n77\_3\_90MHz\_30kHz\_3745MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 13:55:25

n77\_3\_90MHz\_30kHz\_3745MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 14:17:55

n77\_3\_90MHz\_30kHz\_3935MHz\_DFT-s-OFDM  
QPSK\_RB1@244




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 13:56:07

n77\_3\_90MHz\_30kHz\_3935MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 14:19:07

n77\_3\_100MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 13:57:13

n77\_3\_100MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB270@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 14:20:14

n77\_3\_100MHz\_30kHz\_3930MHz\_DFT-s-OFDM  
QPSK\_RB1@272




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:35:47

n77\_3\_100MHz\_30kHz\_3930MHz\_DFT-s-OFDM  
QPSK\_RB270@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:36:12

n78\_1  
n78\_1\_10MHz\_30kHz\_3455MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Testers:Jim Cheng  
Date: 12.JUL.2024 16:26:42

n78\_1\_10MHz\_30kHz\_3455MHz\_DFT-s-OFDM  
QPSK\_RB24@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:27:13

n78\_1\_10MHz\_30kHz\_3545MHz\_DFT-s-OFDM  
QPSK\_RB1@23




ProjectNo.:2401U81808E-RF Testers:Jim Cheng  
Date: 12.JUL.2024 16:27:50

n78\_1\_10MHz\_30kHz\_3545MHz\_DFT-s-OFDM  
QPSK\_RB24@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:28:23

n78\_1\_15MHz\_30kHz\_3457.5MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:29:02

n78\_1\_15MHz\_30kHz\_3457.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:29:34

n78\_1\_15MHz\_30kHz\_3542.5MHz\_DFT-s-OFDM  
QPSK\_RB1@37




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:30:12

n78\_1\_15MHz\_30kHz\_3542.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:30:44

n78\_1\_20MHz\_30kHz\_3460MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:31:23

n78\_1\_20MHz\_30kHz\_3460MHz\_DFT-s-OFDM  
QPSK\_RB50@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:31:55

n78\_1\_20MHz\_30kHz\_3540MHz\_DFT-s-OFDM  
QPSK\_RB1@50




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:32:32

n78\_1\_20MHz\_30kHz\_3540MHz\_DFT-s-OFDM  
QPSK\_RB50@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:33:05

n78\_1\_30MHz\_30kHz\_3465MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:33:53

n78\_1\_30MHz\_30kHz\_3465MHz\_DFT-s-OFDM  
QPSK\_RB75@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:34:25

n78\_1\_30MHz\_30kHz\_3535MHz\_DFT-s-OFDM  
QPSK\_RB1@77



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:35:03


n78\_1\_30MHz\_30kHz\_3535MHz\_DFT-s-OFDM  
QPSK\_RB75@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:35:36




n78\_1\_40MHz\_30kHz\_3470MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:36:50

n78\_1\_40MHz\_30kHz\_3470MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:36:17

n78\_1\_40MHz\_30kHz\_3530MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:38:02

n78\_1\_40MHz\_30kHz\_3530MHz\_DFT-s-OFDM  
QPSK\_RB1@105




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:37:28

n78\_1\_50MHz\_30kHz\_3475MHz\_DFT-s-OFDM  
QPSK\_RB128@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:39:16

n78\_1\_50MHz\_30kHz\_3475MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:39:43

n78\_1\_50MHz\_30kHz\_3525MHz\_DFT-s-OFDM  
QPSK\_RB128@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:40:35

n78\_1\_50MHz\_30kHz\_3525MHz\_DFT-s-OFDM  
QPSK\_RB1@132




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:40:01

n78\_1\_60MHz\_30kHz\_3480MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:41:48

n78\_1\_60MHz\_30kHz\_3480MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:41:16

n78\_1\_60MHz\_30kHz\_3520MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:43:01

n78\_1\_60MHz\_30kHz\_3520MHz\_DFT-s-OFDM  
QPSK\_RB1@161




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:42:27

n78\_1\_70MHz\_30kHz\_3485MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:44:23

n78\_1\_70MHz\_30kHz\_3485MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:43:50

n78\_1\_70MHz\_30kHz\_3515MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:45:44

n78\_1\_70MHz\_30kHz\_3515MHz\_DFT-s-OFDM  
QPSK\_RB1@188




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:45:09

n78\_1\_80MHz\_30kHz\_3490MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:45:53

n78\_1\_80MHz\_30kHz\_3490MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:47:01

n78\_1\_80MHz\_30kHz\_3510MHz\_DFT-s-OFDM  
QPSK\_RB1@216




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:50:12

n78\_1\_80MHz\_30kHz\_3510MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:48:14

n78\_1\_90MHz\_30kHz\_3495MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:47:25

n78\_1\_90MHz\_30kHz\_3495MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:49:28

n78\_1\_90MHz\_30kHz\_3505MHz\_DFT-s-OFDM  
QPSK\_RB1@244




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:48:03

n78\_1\_90MHz\_30kHz\_3505MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:50:41

n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 14:48:45

n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB270@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 12.JUL.2024 16:51:56

n78\_3  
n78\_3\_10MHz\_30kHz\_3705MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:04:14

n78\_3\_10MHz\_30kHz\_3705MHz\_DFT-s-OFDM  
QPSK\_RB24@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:05:45

n78\_3\_10MHz\_30kHz\_3795MHz\_DFT-s-OFDM  
QPSK\_RB1@23




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:22:09

n78\_3\_10MHz\_30kHz\_3795MHz\_DFT-s-OFDM  
QPSK\_RB24@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 12:20:24

n78\_3\_15MHz\_30kHz\_3707.5MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:23:32

n78\_3\_15MHz\_30kHz\_3707.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:24:02

n78\_3\_15MHz\_30kHz\_3792.5MHz\_DFT-s-OFDM  
QPSK\_RB1@37




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:24:35

n78\_3\_15MHz\_30kHz\_3792.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:25:03

n78\_3\_20MHz\_30kHz\_3710MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:26:29

n78\_3\_20MHz\_30kHz\_3710MHz\_DFT-s-OFDM  
QPSK\_RB50@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:26:58

n78\_3\_20MHz\_30kHz\_3790MHz\_DFT-s-OFDM  
QPSK\_RB1@50




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:27:32

n78\_3\_20MHz\_30kHz\_3790MHz\_DFT-s-OFDM  
QPSK\_RB50@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:28:24

n78\_3\_30MHz\_30kHz\_3715MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:28:56

n78\_3\_30MHz\_30kHz\_3715MHz\_DFT-s-OFDM  
QPSK\_RB75@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:29:26

n78\_3\_30MHz\_30kHz\_3785MHz\_DFT-s-OFDM  
QPSK\_RB1@77




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:32:39

n78\_3\_30MHz\_30kHz\_3785MHz\_DFT-s-OFDM  
QPSK\_RB75@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:29:59

n78\_3\_40MHz\_30kHz\_3720MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:31:26

n78\_3\_40MHz\_30kHz\_3720MHz\_DFT-s-OFDM  
QPSK\_RB1@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 11:37:11

n78\_3\_40MHz\_30kHz\_3780MHz\_DFT-s-OFDM  
QPSK\_RB100@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:32:28

n78\_3\_40MHz\_30kHz\_3780MHz\_DFT-s-OFDM  
QPSK\_RB1@105




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:31:59

n78\_3\_50MHz\_30kHz\_3725MHz\_DFT-s-OFDM  
QPSK\_RB128@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:34:22


n78\_3\_50MHz\_30kHz\_3725MHz\_DFT-s-OFDM  
QPSK\_RB1@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:33:52




n78\_3\_50MHz\_30kHz\_3775MHz\_DFT-s-OFDM  
QPSK\_RB128@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:35:26

n78\_3\_50MHz\_30kHz\_3775MHz\_DFT-s-OFDM  
QPSK\_RB1@132




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:34:56

n78\_3\_60MHz\_30kHz\_3730MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:37:21

n78\_3\_60MHz\_30kHz\_3730MHz\_DFT-s-OFDM  
QPSK\_RB1@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:36:51

n78\_3\_60MHz\_30kHz\_3770MHz\_DFT-s-OFDM  
QPSK\_RB162@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:38:32

n78\_3\_60MHz\_30kHz\_3770MHz\_DFT-s-OFDM  
QPSK\_RB1@161




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:39:02

n78\_3\_70MHz\_30kHz\_3735MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:40:28

n78\_3\_70MHz\_30kHz\_3735MHz\_DFT-s-OFDM  
QPSK\_RB1@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:39:58

n78\_3\_70MHz\_30kHz\_3765MHz\_DFT-s-OFDM  
QPSK\_RB180@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:41:38

n78\_3\_70MHz\_30kHz\_3765MHz\_DFT-s-OFDM  
QPSK\_RB1@188




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:41:08

n78\_3\_80MHz\_30kHz\_3740MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 16:07:10

n78\_3\_80MHz\_30kHz\_3740MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:43:36

n78\_3\_80MHz\_30kHz\_3760MHz\_DFT-s-OFDM  
QPSK\_RB1@216




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 16:07:57

n78\_3\_80MHz\_30kHz\_3760MHz\_DFT-s-OFDM  
QPSK\_RB216@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:44:40

n78\_3\_90MHz\_30kHz\_3745MHz\_DFT-s-OFDM  
QPSK\_RB1@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 16:13:23

n78\_3\_90MHz\_30kHz\_3745MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:46:37

n78\_3\_90MHz\_30kHz\_3755MHz\_DFT-s-OFDM  
QPSK\_RB1@244




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 16:14:27

n78\_3\_90MHz\_30kHz\_3755MHz\_DFT-s-OFDM  
QPSK\_RB243@0




ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:47:43

n78\_3\_100MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB1@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 16:18:18

n78\_3\_100MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB270@0



ProjectNo.:2401U81808E-RF Tester:Jim Cheng  
Date: 13.JUL.2024 15:49:39