



n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@0 -36.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:46:40

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@50 -37.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:47:16

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB50@0 -37.32dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:47:51

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:48:54

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@64 -37.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:49:30

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB64@0 -36.58dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:50:07

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:52:12

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@64 -36.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:52:48

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0 -37.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:53:24

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:55:02

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@64 -37.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:56:15

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB64@0 -36.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 09:56:52

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@0 -37.38dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:57:52

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@77 -37.31dBm




ProjectNo.:2401V87401E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:58:30

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB75@0 -37.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 09:59:06

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.46dBm




ProjectNo.:2401V87401E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:00:21

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@77 -36.95dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:00:58

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0 -37.64dBm




ProjectNo.:2401V87401E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:01:34

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@0 -36.80dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:02:50

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@77 -37.32dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:03:26

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB75@0 -37.04dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:04:02

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB100@0 -37.10dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:06:54

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@0 -37.42dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:05:42

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@105 -37.40dBm




ProjectNo.:2401V87404E-RF Testor:Kungfumaster Liang
Date: 11.SEP.2024 10:06:18

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0 -37.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:09:46

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.58dBm




ProjectNo.:2401V87401E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:08:34

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@105 -37.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:09:10

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB100@0 -36.11dBm




ProjectNo.:2401V87401E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:12:43

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:11:28


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@105 -35.37dBm



ProjectNo.:2401V87401E-RF Tester:Kungfumaester Liang
Date: 11.SEP.2024 10:12:04


n41

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.92dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 14:56:59

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -36.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 14:57:36

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -37.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 14:58:13

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 14:58:55

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -36.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 18:21:32

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -37.56dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 14.AUG.2024 18:22:07

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@0 -37.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:22:45

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@23 -37.53dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:23:20

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB24@0 -37.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:23:54

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:25:48

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:26:23

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:26:58

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:27:42

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@37 -37.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:28:22

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0 -36.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:28:58

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@0 -37.62dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:29:41

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37 -37.78dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:30:31

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 -37.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:31:07

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:33:18

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@50 -36.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:33:55

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 -37.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:34:33

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:35:19

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@50 -36.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:36:00

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0 -37.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:36:45

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:37:29

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@50 -37.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:38:05

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0 -36.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:38:41

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@0 -38dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:40:40

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@77 -36.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:41:17

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB75@0 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:41:53

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:42:38

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@77 -37.37dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:43:15

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0 -37.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:43:52

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.67dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:44:34

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@77 -35.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:45:10

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 -37.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:45:47

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 -37.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:49:02

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:47:47

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@105 -37.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:48:25

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0 -37.37dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:50:58

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.53dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:49:44

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@105 -37.61dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:50:21

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB100@0 -37.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:52:54

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:51:40

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@105 -37.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:52:17

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0 -37.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:56:02

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.12dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:54:48

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@132 -37.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:55:26

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0 -37.82dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:58:03

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.01dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:56:48

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@132 -37.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 18:57:26

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB128@0 -37.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:10:35

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.47dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:09:03

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@132 -37.62dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:09:49

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB162@0 -37.82dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:11:52

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@0 -34.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:10:35

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@161 -37.36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:11:13

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0 -37.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:13:56

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.88dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:12:37

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@161 -34.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:13:17

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0 -37.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:16:00

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.02dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:14:40

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161 -37.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:15:21

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@0 -35.30dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:17:36

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@216 -37.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:18:16

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0 -37.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:18:55

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:19:40

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@216 -35.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:20:21

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0 -36.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:21:00

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.07dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:21:46

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216 -37.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:22:26

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0 -37.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:23:05

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@0 -36.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:24:40

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@244 -38.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:25:20

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB243@0 -38.01dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:26:00

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.30dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 00:16:31

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@244 -37.28dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:16:50

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB243@0 -37.09dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:17:35

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@0 -35.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:18:27

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244 -36.95dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:19:14

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0 -37.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:19:59

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0 -36.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:50:37

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@272 -34.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:51:18

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0 -37.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:51:59

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:52:45

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@272 -37.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:53:27

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB270@0 -37.63dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:54:08

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@0 -37.55dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:54:54

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272 -36.94dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:55:37


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0 -37.77dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:56:18


n66

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.52dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:58:03

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.08dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:58:38

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 19:59:13

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.62dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:21:39

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@24 -37.27dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:22:19

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB25@0 -36.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:22:59

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:12:13

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.02dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:12:49

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:13:24

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@0 -36.95dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:15:24

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@51 -36.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:16:00

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB50@0 -36.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:16:36

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:23:42

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@51 -37.36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:24:22

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB50@0 -36.50dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:25:02

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@0 -36.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:31:02

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@51 -37.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:31:39

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB50@0 -36.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:32:15

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.16dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:33:49

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:34:26

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:35:01

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.56dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:25:45

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@78 -36.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:26:26

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB75@0 -37.24dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:27:06

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.77dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:49:33

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:50:09

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:50:46

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB100@0 -36.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:53:45

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@0 -37.41dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:52:32

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@105 -37.42dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:53:09