



n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB100@0 -42.952MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:08:11


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@105 -26.265MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:07:31


n41

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@0 -30.500MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:10:00

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -36.621MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:10:38

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@23 -33.594MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:11:28

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB24@0 -37.520MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:12:08

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@0 -30.074MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:13:39

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB36@0 -34.902MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:14:15

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37 -30.131MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:14:57

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 -39.683MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:15:36

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@0 -38.937MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 13:06:18

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 -38.295MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:20:32

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@50 -37.284MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:21:20

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0 -40.333MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:22:00

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@0 -38.576MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:23:33

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB75@0 -40.763MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:24:14

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@77 -39.302MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:25:01

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 -40.939MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:25:39

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 -41.357MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:28:14

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@0 -34.576MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:27:37

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB100@0 -42.351MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:29:41

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@105 -36.453MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:29:02

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0 -41.683MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:31:50

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@0 -40.349MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:31:12

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB128@0 -42.123MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:33:14

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@132 -39.428MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:32:34

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB162@0 -42.201MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:35:54

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@0 -37.185MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:35:16

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0 -42.882MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:37:15

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161 -38.855MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 12:36:37

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@0 -29.170MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:39:17

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0 -43.667MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:39:55

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216 -28.764MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:40:38

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0 -44.205MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:41:17

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@0 -25.773MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:42:50

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB243@0 -43.742MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:43:28

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244 -25.945MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:44:18

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0 -44.094MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:45:03

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0 -25.517MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:47:12

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0 -43.863MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:47:50

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272 -26.747MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:48:35


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0 -44.946MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 12:49:14


n66

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@0 -28.447MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:51:07

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB25@0 -38.139MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:51:44

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@24 -31.244MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:07:44

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.419MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:08:22

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@0 -35.451MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 12:59:36

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB50@0 -40.392MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:00:14

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@51 -38.124MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:09:54

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB50@0 -39.386MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:10:32

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@0 -32.239MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:12:02

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB75@0 -42.380MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:12:39

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@78 -35.459MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:13:51

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB75@0 -41.103MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:14:27

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB100@0 -42.611MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:17:55

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@0 -34.533MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:17:21

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB100@0 -41.970MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:19:24

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@105 -34.804MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:18:47

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB128@0 -41.786MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:21:41

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@0 -34.152MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:21:02

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB128@0 -40.952MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:23:05

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@132 -38.984MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:22:28

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB160@0 -42.780MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:26:03

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB1@0 -28.967MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:25:25

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB160@0 -42.561MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:27:24

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@159 -31.872MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 13:26:46

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB1@0 -22.852MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:29:42

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB216@0 -43.174MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:30:21

n66_40MHz_15kHz_1760MHz_DFT-s-OFDM
QPSK_RB1@215 -24.879MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:32:38


n66_40MHz_15kHz_1760MHz_DFT-s-OFDM
QPSK_RB216@0 -42.106MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 13:33:17


n77_1

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -46.646MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:29:19

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -46.589MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:30:02

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -46.798MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:30:49

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -47.063MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:31:31

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.989MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:32:20

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -46.946MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:33:01

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -44.844MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:33:47

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.199MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:34:27

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -46.968MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:35:17

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -47.130MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:36:01

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -47.240MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:36:48

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -47.304MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:37:30

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -44.334MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:38:20

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -47.007MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:39:05

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -41.746MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:39:58

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -47.368MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:40:41

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -47.201MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:42:14

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -36.561MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:41:31

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -47.392MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 14:43:46

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -36.959MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 23.AUG.2024 11:43:03