




n38_25MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB65@0 23.215MHz




n38_25MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB65@0 23.229MHz




n38_25MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB65@0 23.218MHz




n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB64@0 23.125MHz




n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB64@0 23.011MHz




n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM 16
QAM_RB64@0 23.030MHz




n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM 64
QAM_RB64@0 23.035MHz




n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM 256
QAM_RB64@0 23.029MHz




n38_25MHz_30kHz_2607.5MHz_CP-OFDM
QPSK_RB65@0 23.227MHz




n38_25MHz_30kHz_2607.5MHz_CP-OFDM 16
QAM_RB65@0 23.211MHz




n38_25MHz_30kHz_2607.5MHz_CP-OFDM 64
QAM_RB65@0 23.229MHz




n38_25MHz_30kHz_2607.5MHz_CP-OFDM 256
QAM_RB65@0 23.205MHz




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.619MHz




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB75@0 27.522MHz




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM 16
QAM_RB75@0 27.748MHz




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM 64
QAM_RB75@0 27.649MHz




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM 256
QAM_RB75@0 27.537MHz




n38_30MHz_30kHz_2585MHz_CP-OFDM
QPSK_RB78@0 27.863MHz




n38_30MHz_30kHz_2585MHz_CP-OFDM 16
QAM_RB78@0 27.849MHz




n38_30MHz_30kHz_2585MHz_CP-OFDM 64
QAM_RB78@0 27.763MHz




n38_30MHz_30kHz_2585MHz_CP-OFDM 256
QAM_RB78@0 27.766MHz




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.621MHz




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0 27.629MHz




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB75@0 27.741MHz




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB75@0 27.656MHz




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB75@0 27.515MHz




n38_30MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB78@0 27.856MHz




n38_30MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB78@0 27.776MHz




n38_30MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB78@0 27.752MHz




n38_30MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB78@0 27.766MHz




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.606MHz




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB75@0 27.606MHz




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM 16
QAM_RB75@0 27.744MHz



n38_30MHz_30kHz_2605MHz_DFT-s-OFDM 64
QAM_RB75@0 27.622MHz



n38_30MHz_30kHz_2605MHz_DFT-s-OFDM 256
QAM_RB75@0 27.504MHz



n38_30MHz_30kHz_2605MHz_CP-OFDM
QPSK_RB78@0 27.877MHz

