




n41\_10MHz\_30kHz\_2501.01MHz\_CP-OFDM 16  
QAM\_RB24@0 8.564MHz




n41\_10MHz\_30kHz\_2501.01MHz\_CP-OFDM 64  
QAM\_RB24@0 8.565MHz




n41\_10MHz\_30kHz\_2501.01MHz\_CP-OFDM 256  
QAM\_RB24@0 8.610MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.567MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.576MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.579MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.538MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.563MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB24@0 8.603MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB24@0 8.574MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB24@0 8.576MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB24@0 8.611MHz




n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.571MHz




n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.610MHz




n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.576MHz




n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.580MHz




n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.565MHz




n41\_10MHz\_30kHz\_2685MHz\_CP-OFDM  
QPSK\_RB24@0 8.575MHz




n41\_10MHz\_30kHz\_2685MHz\_CP-OFDM 16  
QAM\_RB24@0 8.572MHz




n41\_10MHz\_30kHz\_2685MHz\_CP-OFDM 64  
QAM\_RB24@0 8.572MHz




n41\_10MHz\_30kHz\_2685MHz\_CP-OFDM 256  
QAM\_RB24@0 8.610MHz




n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.463MHz




n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.469MHz




n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.466MHz




n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.453MHz




n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.503MHz




n41\_15MHz\_30kHz\_2503.5MHz\_CP-OFDM  
QPSK\_RB38@0 13.569MHz




n41\_15MHz\_30kHz\_2503.5MHz\_CP-OFDM 16  
QAM\_RB38@0 13.574MHz




n41\_15MHz\_30kHz\_2503.5MHz\_CP-OFDM 64  
QAM\_RB38@0 13.580MHz



n41\_15MHz\_30kHz\_2503.5MHz\_CP-OFDM 256  
QAM\_RB38@0 13.528MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.451MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.458MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.469MHz



n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.467MHz



n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.462MHz



n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB38@0 13.567MHz

