




n41_15MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB38@0 13.575MHz




n41_15MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB38@0 13.569MHz




n41_15MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB38@0 13.589MHz




n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.448MHz




n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 13.447MHz




n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM 16
QAM_RB36@0 13.517MHz




n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM 64
QAM_RB36@0 13.504MHz




n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM 256
QAM_RB36@0 13.453MHz




n41_15MHz_30kHz_2682.48MHz_CP-OFDM
QPSK_RB38@0 13.579MHz




n41_15MHz_30kHz_2682.48MHz_CP-OFDM 16
QAM_RB38@0 13.562MHz




n41_15MHz_30kHz_2682.48MHz_CP-OFDM 64
QAM_RB38@0 13.585MHz




n41_15MHz_30kHz_2682.48MHz_CP-OFDM 256
QAM_RB38@0 13.571MHz




n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.033MHz




n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 18.023MHz




n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM 16
QAM_RB50@0 18.095MHz




n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM 64
QAM_RB50@0 18.030MHz




n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM 256
QAM_RB50@0 18.080MHz




n41_20MHz_30kHz_2506.02MHz_CP-OFDM
QPSK_RB51@0 18.170MHz




n41_20MHz_30kHz_2506.02MHz_CP-OFDM 16
QAM_RB51@0 18.178MHz




n41_20MHz_30kHz_2506.02MHz_CP-OFDM 64
QAM_RB51@0 18.186MHz




n41_20MHz_30kHz_2506.02MHz_CP-OFDM 256
QAM_RB51@0 18.190MHz




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.032MHz




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0 18.025MHz




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB50@0 18.029MHz




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB50@0 18.029MHz




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB50@0 18.029MHz




n41_20MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB51@0 18.176MHz




n41_20MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB51@0 18.167MHz




n41_20MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB51@0 18.179MHz




n41_20MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB51@0 18.185MHz




n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.085MHz




n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0 18.100MHz




n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM 16
QAM_RB50@0 18.161MHz



n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM 64
QAM_RB50@0 18.033MHz



n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM 256
QAM_RB50@0 18.033MHz



n41_20MHz_30kHz_2679.99MHz_CP-OFDM
QPSK_RB51@0 18.183MHz

