




n66\_25MHz\_15kHz\_1722.5MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 23.439MHz




n66\_25MHz\_15kHz\_1722.5MHz\_DFT-s-OFDM  
QPSK\_RB128@0 23.344MHz




n66\_25MHz\_15kHz\_1722.5MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 23.507MHz




n66\_25MHz\_15kHz\_1722.5MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 23.430MHz




n66\_25MHz\_15kHz\_1722.5MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 23.432MHz




n66\_25MHz\_15kHz\_1722.5MHz\_CP-OFDM  
QPSK\_RB133@0 23.649MHz




n66\_25MHz\_15kHz\_1722.5MHz\_CP-OFDM 16  
QAM\_RB133@0 23.731MHz




n66\_25MHz\_15kHz\_1722.5MHz\_CP-OFDM 64  
QAM\_RB133@0 23.706MHz




n66\_25MHz\_15kHz\_1722.5MHz\_CP-OFDM 256  
QAM\_RB133@0 23.708MHz




n66\_25MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 23.523MHz




n66\_25MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB128@0 23.439MHz




n66\_25MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 23.434MHz




n66\_25MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 23.432MHz




n66\_25MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 23.530MHz




n66\_25MHz\_15kHz\_1745MHz\_CP-OFDM  
QPSK\_RB133@0 23.704MHz




n66\_25MHz\_15kHz\_1745MHz\_CP-OFDM 16  
QAM\_RB133@0 23.731MHz




n66\_25MHz\_15kHz\_1745MHz\_CP-OFDM 64  
QAM\_RB133@0 23.711MHz




n66\_25MHz\_15kHz\_1745MHz\_CP-OFDM 256  
QAM\_RB133@0 23.640MHz




n66\_25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 23.519MHz




n66\_25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM  
QPSK\_RB128@0 23.608MHz




n66\_25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 23.407MHz




n66\_25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 23.505MHz




n66\_25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 23.603MHz




n66\_25MHz\_15kHz\_1767.5MHz\_CP-OFDM  
QPSK\_RB133@0 23.708MHz




n66\_25MHz\_15kHz\_1767.5MHz\_CP-OFDM 16  
QAM\_RB133@0 23.713MHz




n66\_25MHz\_15kHz\_1767.5MHz\_CP-OFDM 64  
QAM\_RB133@0 23.709MHz




n66\_25MHz\_15kHz\_1767.5MHz\_CP-OFDM 256  
QAM\_RB133@0 23.727MHz




n66\_30MHz\_15kHz\_1725MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB160@0 28.566MHz




n66\_30MHz\_15kHz\_1725MHz\_DFT-s-OFDM  
QPSK\_RB160@0 28.491MHz



n66\_30MHz\_15kHz\_1725MHz\_DFT-s-OFDM 16  
QAM\_RB160@0 28.460MHz




n66\_30MHz\_15kHz\_1725MHz\_DFT-s-OFDM 64  
QAM\_RB160@0 28.578MHz




n66\_30MHz\_15kHz\_1725MHz\_DFT-s-OFDM 256  
QAM\_RB160@0 28.483MHz




n66\_30MHz\_15kHz\_1725MHz\_CP-OFDM  
QPSK\_RB160@0 28.563MHz



n66\_30MHz\_15kHz\_1725MHz\_CP-OFDM 16  
QAM\_RB160@0 28.468MHz



n66\_30MHz\_15kHz\_1725MHz\_CP-OFDM 64  
QAM\_RB160@0 28.466MHz



n66\_30MHz\_15kHz\_1725MHz\_CP-OFDM 256  
QAM\_RB160@0 28.490MHz

