




n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM 64
QAM_RB100@0 37.288MHz




n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM 256
QAM_RB100@0 37.306MHz




n78_1_40MHz_30kHz_3470MHz_CP-OFDM
QPSK_RB106@0 37.788MHz




n78_1_40MHz_30kHz_3470MHz_CP-OFDM 16
QAM_RB106@0 37.780MHz




n78_1_40MHz_30kHz_3470MHz_CP-OFDM 64
QAM_RB106@0 37.814MHz




n78_1_40MHz_30kHz_3470MHz_CP-OFDM 256
QAM_RB106@0 37.772MHz




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.603MHz




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 37.475MHz




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB100@0 37.445MHz




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB100@0 37.170MHz




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB100@0 37.299MHz



n78_1_40MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB106@0 37.788MHz




n78_1_40MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB106@0 37.799MHz




n78_1_40MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB106@0 37.818MHz




n78_1_40MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB106@0 37.784MHz




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.604MHz




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 37.605MHz




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM 16
QAM_RB100@0 37.343MHz




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM 64
QAM_RB100@0 37.192MHz




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM 256
QAM_RB100@0 37.319MHz




n78_1_40MHz_30kHz_3530MHz_CP-OFDM
QPSK_RB106@0 37.776MHz




n78_1_40MHz_30kHz_3530MHz_CP-OFDM 16
QAM_RB106@0 37.789MHz




n78_1_40MHz_30kHz_3530MHz_CP-OFDM 64
QAM_RB106@0 37.819MHz




n78_1_40MHz_30kHz_3530MHz_CP-OFDM 256
QAM_RB106@0 37.794MHz




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.063MHz




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 46.697MHz




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 16
QAM_RB128@0 47.059MHz




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 64
QAM_RB128@0 47.012MHz




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 256
QAM_RB128@0 46.841MHz




n78_1_50MHz_30kHz_3475MHz_CP-OFDM
QPSK_RB133@0 47.416MHz




n78_1_50MHz_30kHz_3475MHz_CP-OFDM 16
QAM_RB133@0 47.426MHz




n78_1_50MHz_30kHz_3475MHz_CP-OFDM 64
QAM_RB133@0 47.412MHz



n78_1_50MHz_30kHz_3475MHz_CP-OFDM 256
QAM_RB133@0 47.297MHz



n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.001MHz



n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 46.826MHz



n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB128@0 47.010MHz

