



n38\_40MHz\_30kHz\_2595MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.476MHz




n38\_40MHz\_30kHz\_2595MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.606MHz



n38\_40MHz\_30kHz\_2595MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.291MHz




n38\_40MHz\_30kHz\_2595MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.196MHz



n38\_40MHz\_30kHz\_2595MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.290MHz





n38\_40MHz\_30kHz\_2595MHz\_CP-OFDM  
QPSK\_RB106@0 37.770MHz



n38\_40MHz\_30kHz\_2595MHz\_CP-OFDM 16  
QAM\_RB106@0 37.779MHz



n38\_40MHz\_30kHz\_2595MHz\_CP-OFDM 64  
QAM\_RB106@0 37.815MHz



n41



n38\_40MHz\_30kHz\_2595MHz\_CP-OFDM 256  
QAM\_RB106@0 37.768MHz

n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.573MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.579MHz


n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.601MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.538MHz




n41\_10MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.561MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB24@0 8.539MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB24@0 8.572MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB24@0 8.572MHz




n41\_10MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB24@0 8.614MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.468MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.451MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.520MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.456MHz




n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.468MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB38@0 13.569MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB38@0 13.578MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB38@0 13.574MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB38@0 13.560MHz



n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.098MHz



n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.030MHz



n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.036MHz

