



n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -40.48dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:25:40

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -40.71dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:26:41

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -41.13dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:27:50

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -40.79dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:28:49

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -41.06dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:29:49

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -40.71dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:40:20

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -40.64dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:41:19

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -39.60dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:42:19

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.49dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:43:24

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -40.64dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:44:25

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -41.05dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:45:26

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -41.06dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:46:31

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -40.74dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:47:32

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -41.02dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:48:32

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -41.03dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:51:43

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -40.57dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:49:41

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -40.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:50:42

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -40.65dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:54:50

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.75dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:52:45

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -41.03dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:53:50

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -40.85dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:57:58

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -41.18dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:55:57

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -40.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:56:57

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -40.82dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:01:08

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -40.92dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:59:06

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -41.09dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:00:07

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -40.93dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:04:14

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.27dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:02:13

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -40.88dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:03:13

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -40.59dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:07:22

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -40.75dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:05:21

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -40.42dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:06:21

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -40.62dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:10:34

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -40.56dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:08:32

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -40.41dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:09:33

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -40.72dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:13:47

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.50dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:11:44

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -40.64dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:12:45

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -40.68dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:16:55

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -41.02dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:14:52

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -40.48dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:15:53

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -40.90dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:20:05

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -40.70dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:18:03

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -40.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:19:04

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -40.94dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:23:13

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.76dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:21:10

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -41dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:22:11

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -40.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:26:21

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -40.10dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:24:19

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -40.24dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:25:20

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -40.86dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:27:30

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -39.65dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:28:31

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -41dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:29:33

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.13dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 05:30:39

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -40.64dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:31:41

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -40.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:32:42

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@0 -40.83dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:33:48

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -40.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:34:50

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -39.76dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:35:51

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -40.60dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 05:37:00