

Tesla, Inc.
3500 Deer Creek Road
Palo Alto, California
U.S.A.



Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Date: October 16, 2023

Hereby declare that products in the table below are hardware identical with no hardware change, only change model name and use software to activate BLE, UHF and NFC function and those function do not transmit at the same time so the UHF test report (FCC Report number: FR230315009 / ISED report number: CR230315009) from the original model (FCC ID: 2AEIM-1735511UHF) / (ISED ID : 20098-1735511UHF) is still representative for the new model (FCC ID: 2AEIM-1735511) / (ISED ID: 20098-1735511UHF) and demonstrates compliance.

Model	FCC ID	ISED ID	Support RF function	Difference
Magic Dock Wall Connector	2AEIM-1735511UHF	20098-1735511UHF	UHF	Only change model name and use software turn on
Universal Wall Connector	2AEIM-1735511	20098-1735511	UHF,BLE,NFC	BLE and NFC, no any hardware change.

Sincerely,

A handwritten signature in black ink, appearing to read 'Viraj Kurundu', with a horizontal line drawn underneath it.

Viraj Andrabadu Kurundu Patabendige
Sr Manager, Compliance Engineering
vandrabadukurundu@tesla.com

