

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230



Figure 1. Front Side of PCB in Enclosure

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230




Figure 2. Back Side of PCB in Enclosure

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230



Figure 3. Front Side of PCB, Outside Enclosure

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230



Figure 4. Back Side of PCB, Outside Enclosure

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230




Figure 5. Bowtie Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230




Figure 6. EUT with no USB Access (Top view)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230




Figure 7. EUT with no USB Access (HT5200)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230




Figure 8. EUT with USB Access Port (Top View)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change
2AEP2-THAWK1
20168-THAWK1
20-0112
April 17, 2020
Headsight Inc
HT5200 and HT5230



Figure 9. EUT with USB Access Port (HT5230)