


Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 1 of 9




Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 2 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 3 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 4 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 5 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 6 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 7 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 8 of 9





Internal Photos of EUT

Report No.: CN218ZQB 001

Model No. : A9K

Page: 9 of 9



--THE END--