






# 单VTA-204B-MAH (TT32E-MAH) 背板铭牌生产图

<p><b>VICTROLA™</b> www.victrola.com</p> <p>MODEL:VTA-204B HVIN:VTA-204B.1 MUSIC CENTER WITH BLUETOOTH FREQ. RANGE: FM: 88-108MHz POWER SUPPLY: AC 120V~60Hz POWER CONSUMPTION: 30W MADE IN CHINA SERIAL NUMBER:</p>	<p> <b>CAUTION/ATTENTION:</b> RISK OF ELECTRIC SHOCK. DO NOT OPEN. / ATTENTION RISQUE DE CHOC ÉLECTRIQUE. NE PAS OUVRIR. </p> <p><b>CAUTION/ATTENTION:</b> TO REDUCE THE RISK OF ELECTRIC SHOCK, DO NOT REMOVE COVER (OR BACK). NO USER SERVICEABLE PARTS INSIDE. REFER SERVICING TO QUALIFIED SERVICE PERSONNEL. POUR RÉDUIRE LE RISQUE DE CHOC ÉLECTRIQUE, NE PAS RETIRER LA COUVERCLE (OU L'ARRIÈRE). CONFIER L'ENTRETIEN À UN PERSONNEL QUALIFIÉ. AUCUNE PIÈCES À L'INTÉRIEUR RÉPARABLES.</p> <p> <b>Complies with UL 62368</b> CAN/CSA-C22.2 No.62368</p> <p> </p> <p>C US CU72205057</p>	<p> <b>WARNING / AVERTISSEMENT:</b> This product can expose you to chemicals including Diisononyl phthalate (DINP), which is known to the State of California to cause cancer. For more information go to <a href="http://www.P65Warnings.ca.gov">www.P65Warnings.ca.gov</a>. / Ce produit peut vous exposer à des produits chimiques, notamment le phtalate de Diisononyle (DINP), qui est connu dans l'État de Californie pour provoquer le cancer. Pour plus d'informations, visitez <a href="http://www.P65Warnings.ca.gov">www.P65Warnings.ca.gov</a></p>
<p>FCC ID: 2AFHW-VTA-204BTO IC: 9577A-VTA204BTO CAN ICES-3(B)/NMB-3(B)</p> <p>This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p>	<p><b>CLASS 1 LASER PRODUCT</b></p>	<p>Complies with 21 CFR 1040.10 and 1040.11 except for deviations pursuant to Laser Notice No.50, dated June 24, 2007</p>

尺寸:140x48.17 mm