



10MHz_High_QPSK_1@49




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:17:44

10MHz_High_QPSK_50@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:18:22

10MHz_High_16QAM_1@49




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:19:01

10MHz_High_16QAM_50@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:19:40

15MHz_Low_QPSK_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:22:23

15MHz_Low_QPSK_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
 Date: 18.SEP.2024 16:23:02

15MHz_Low_16QAM_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:23:40

15MHz_Low_16QAM_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:24:18

15MHz_High_QPSK_1@74




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:25:24

15MHz_High_QPSK_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:26:02

15MHz_High_16QAM_1@74




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:26:40

15MHz_High_16QAM_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:27:18

20MHz_Low_QPSK_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:29:46

20MHz_Low_QPSK_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:30:25

20MHz_Low_16QAM_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:31:04

20MHz_Low_16QAM_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:31:42

20MHz_High_QPSK_1@99




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:33:01

20MHz_High_QPSK_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:33:42

20MHz_High_16QAM_1@99



ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:34:22

20MHz_High_16QAM_100@0



ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 16:35:03


Spurious Emissions at Antenna Terminal

FCC Part 22H

B5 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:48:09

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:48:28

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:48:48

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:49:12

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:49:34

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:49:57

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:50:23

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:50:47

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:51:12

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:51:40

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:52:05

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:52:31

FCC Part 27


B41 , Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




5MHz_High_QPSK_1@0(30MHz~27.9GHz)




10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



10MHz_High_QPSK_1@0(30MHz~27.9GHz)




15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 13:59:24

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:00:02

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 14:00:43

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:01:25

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 14:02:04

20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long
Date: 18.SEP.2024 11:02:45