



Setup Photos


Revision	Report Date	Reason for Revision
∅	July 1, 2021	Initial Issue.




Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup



Substitution Method, Test Setup



30MHz – 1GHz, Part15B Test Setup



Conducted Power Measurement Test Setup