

CN100

F83

battMeasEn HVEen HULSel battMeas alarmDet MemDetSet RF1 CS MISO CLK MOSI G002 rstCC1125

PGEC PGED TX USBQ RTS GND MAC-IP UCC MCLR RX CTS SCL

1ntTamper PORTF4 PORTF5 PORTF6 G000 buttPair buttSiltst buttCallP buttBkTamp

detTampEn detTamp hiVoltSirenEn alarmDetIn SirenSwitchedGND HV

Green IO1-IO0

buttCallPnt\_In

VBAT

buttBkTamp\_In

