



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:42:45

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:42:55

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:43:07

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:43:17

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:43:30

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:43:40

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:44:50

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:45:36

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:45:49

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:34:39

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:46:14

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:35:27

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:48:45

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:36:22

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 16:49:08


Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 22.AUG.2022 15:38:23




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:49:30

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:37:58

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:50:18

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:39:24

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:50:41

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:39:53

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:51:40

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:40:26

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:52:29

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:52:39

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:52:52

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:53:02

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:53:15

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:53:25

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 16:54:48


Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 12.AUG.2022 16:54:58




Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:55:12

Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:55:22

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:55:35

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:55:45

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:56:01

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:56:11

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:56:24

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:56:34

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:56:49

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:56:59

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:58:18

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:58:28

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 16:58:42

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 16:58:52

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 16:59:05


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 12.AUG.2022 16:59:15




Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 17:00:30

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 17:00:40

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 17:00:53

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 17:01:03

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 17:01:16

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 17:01:26

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 17:02:03

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 12.AUG.2022 17:02:13

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 17:02:26

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:48:23

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 18:13:16


Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 12.AUG.2022 18:13:26




Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 18:14:30


Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 22.AUG.2022 15:43:11




Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:14:54

Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:43:43

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:16:00

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:44:35

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:16:23

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:46:19

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:16:46

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 22.AUG.2022 15:46:00

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:26:12

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:26:22

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:26:34

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:26:44

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:27:00

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:27:10

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 18:27:47


### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 12.AUG.2022 18:27:57




Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:28:09

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:28:19

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:28:32

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:28:42

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:29:56

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:30:06

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:30:19

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:30:29

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:30:41

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:30:51

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:33:32

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:33:42

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.AUG.2022 18:33:55

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.AUG.2022 18:34:05

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 12.AUG.2022 18:34:18

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 12.AUG.2022 18:34:28