

BIO-key Hong Kong Limited





Request for Class II Permissive Change

FCC ID: 2AIKJ-BL

Date: Oct. 26, 2017

TO: Federal Communication Commission

Please be notified that we, the undersigned, BIO-key Hong Kong Limited declare that the reasons for this Class II permissive change are as below:

Original device (model BL0509)	New device (model BL1209)
<p>Compared with the new device, NO RF circuit change and there are no such parts marked within red lines like the new device, since S3(a switch) is just on the main PCB board.</p> <p>The function of S3 are the same for both original device and new device</p> 	<p>Compared with Original device, NO RF circuit change and these parts marked within red lines is for S3(a switch) to connect to main PCB board.</p> <p>The function of S3 are the same for both original device and new device</p> 
<p>Other differences between the two device are:</p> <ol style="list-style-type: none"> 1. Color. 2. the size of shape. 3. the size of motor. 4. the capacity of battery. 5. some peripheral circuit components layout(such as model BL0509's S3 is on the <div style="display: flex; align-items: center;">  <div style="margin-left: 10px;"> <p>main board</p>  <p>), but model BL0509's S3 apart the main board and connect to the main board with wires</p> </div> </div>	

6. some peripheral circuit components parameters(such as the capacity of C1



1uF is for BL1209,



0.1uF is for BL0509)

Thank you.
Sincerely.

Dated this 2017-10-26

By:

Pan Wong

Signature

Printed

Title: General Manager

On behalf of : BIO-key Hong Kong Limited

Telephone: +852 90300848