



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:23:27

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:23:38

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:23:54

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:24:05

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:24:18

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:24:29

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:24:43

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:24:54

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:25:10

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:25:21

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:25:34

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:25:45

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:26:01

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:26:12

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:26:25

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:26:36

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:26:49

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:27:00

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:27:18

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:27:29

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:27:42

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:27:53

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:28:10

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:28:21

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:28:40

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:28:51

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:29:05

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:29:16

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:29:30

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:29:41

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:29:56

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:30:07

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:30:24

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:30:35

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:30:49

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:31:00

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:31:17

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:31:28

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:31:41

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:31:51

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:32:08

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:32:19

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:32:37

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:32:48

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:33:25

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:33:36

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:33:52

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:34:03

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:34:16

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:34:27

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:34:43

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:34:54

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:35:10

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:35:21

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:35:35

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:35:45

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:35:59

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:36:10

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:36:27

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:36:37

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:36:51

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:37:02

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:37:19

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:37:30

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:37:50

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:38:01

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:38:15

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:38:26

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:38:43

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.DEC.2022 10:38:54

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:39:10

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:39:21

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:39:37

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:39:48

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:40:01

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:40:12

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:40:31

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:40:42

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:40:56

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:41:10

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:41:27

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:41:38

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:41:56

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:42:07

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:42:24

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:42:35

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:42:49

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:43:00

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:43:16

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:43:27

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:43:41

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:43:52

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.DEC.2022 10:44:06

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.DEC.2022 10:44:17

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:53:51

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:19:05

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:54:52

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:17:56

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:55:16

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:19:59

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:56:14

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:20:35

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:56:39

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:21:18

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:57:07

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:21:50

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:58:57

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:22:35

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:59:22

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:23:06

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.DEC.2022 11:59:50

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:24:00

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.DEC.2022 12:01:05

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:25:18

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.DEC.2022 12:01:34

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:26:00

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.DEC.2022 12:02:02

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.55GHz)




Date: 28.DEC.2022 18:26:39

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:55:47

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:55:58

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:56:13

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:56:24

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:57:43

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:57:53

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:58:08

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:58:19

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:58:35

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:58:46

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:59:02

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:59:13

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:59:30

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.DEC.2022 13:59:44

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 13:59:58

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.DEC.2022 14:00:08

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.DEC.2022 14:00:22

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.DEC.2022 14:00:32

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 14:00:47

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 1.DEC.2022 14:00:58

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 14:01:15

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 1.DEC.2022 14:01:26

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.DEC.2022 14:01:39

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 1.DEC.2022 14:01:53

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:48:33

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:48:43

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:48:57

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:49:08

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:49:21

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:49:32

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:49:47

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:49:58

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:50:14

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:50:25

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:50:42

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:50:53

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:51:12

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:51:23

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:51:40

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:51:51

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:52:08

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:52:19

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:52:38

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:52:48

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 9.JAN.2023 15:53:03

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 9.JAN.2023 15:53:14

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 9.JAN.2023 15:53:30

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 9.JAN.2023 15:53:43