



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 10.MAR.2022 16:36:51

Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 10.MAR.2022 16:37:06

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 10.MAR.2022 16:37:36

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 10.MAR.2022 16:37:55

Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 10.MAR.2022 16:38:19

Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 10.MAR.2022 16:38:35

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 10.MAR.2022 16:38:54

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 10.MAR.2022 16:39:12

Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 10.MAR.2022 16:39:36

Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 10.MAR.2022 16:40:08

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 10.MAR.2022 16:41:23

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 10.MAR.2022 16:41:42

Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 10.MAR.2022 16:42:09

Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 10.MAR.2022 16:42:33

Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 10.MAR.2022 16:43:00


Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 10.MAR.2022 16:43:29




Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 10.MAR.2022 16:44:03

Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 10.MAR.2022 16:44:35

Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 10.MAR.2022 16:45:00

Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 10.MAR.2022 16:45:34

Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 10.MAR.2022 16:46:12

Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 10.MAR.2022 16:46:43

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 10.MAR.2022 16:47:22

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 10.MAR.2022 16:47:52

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 10.MAR.2022 16:48:20

Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 10.MAR.2022 16:48:41

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 10.MAR.2022 16:49:12

Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 10.MAR.2022 16:49:37

Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 10.MAR.2022 16:49:57

Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 10.MAR.2022 16:50:15

Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 10.MAR.2022 16:50:37


Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 10.MAR.2022 16:50:52




Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 10.MAR.2022 16:51:16

Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 10.MAR.2022 16:51:37

Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 10.MAR.2022 16:51:56

Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 10.MAR.2022 16:52:14

Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 10.MAR.2022 16:52:39

Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 10.MAR.2022 16:53:09

Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 10.MAR.2022 16:53:38

Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 10.MAR.2022 16:54:07

Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 10.MAR.2022 16:54:41

Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 10.MAR.2022 16:55:15

Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 10.MAR.2022 16:55:47

Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 10.MAR.2022 16:56:15

Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 10.MAR.2022 16:57:25

Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 10.MAR.2022 16:58:00

Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 10.MAR.2022 16:58:32


Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 10.MAR.2022 16:59:01




Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 10.MAR.2022 16:59:21

Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 10.MAR.2022 16:59:36

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 11.MAR.2022 10:49:07

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 11.MAR.2022 10:50:05

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 11.MAR.2022 10:51:14

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 11.MAR.2022 10:51:53

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 11.MAR.2022 10:53:19

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 11.MAR.2022 10:54:00

Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 11.MAR.2022 10:56:01

Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 11.MAR.2022 10:56:57

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 11.MAR.2022 10:58:42

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 11.MAR.2022 10:59:39

Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 10.MAR.2022 17:04:25

Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 10.MAR.2022 17:04:54

Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 10.MAR.2022 17:05:21


Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 10.MAR.2022 17:05:43




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 10.MAR.2022 17:06:08

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 10.MAR.2022 17:06:30

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 10.MAR.2022 17:06:56

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 10.MAR.2022 17:07:14

Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 10.MAR.2022 17:07:43

Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 10.MAR.2022 17:08:15

Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 10.MAR.2022 17:08:39

Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 10.MAR.2022 17:09:11

Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 10.MAR.2022 17:09:45

Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 10.MAR.2022 17:10:16

Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 10.MAR.2022 17:10:48

Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 10.MAR.2022 17:11:26

Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 10.MAR.2022 17:12:14

Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 10.MAR.2022 17:12:45

Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 10.MAR.2022 17:13:18


Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 10.MAR.2022 17:13:46




Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 11.MAR.2022 09:20:31

Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 11.MAR.2022 10:40:18

Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 11.MAR.2022 09:21:04

Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 11.MAR.2022 09:21:21

Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 11.MAR.2022 09:21:41

Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 11.MAR.2022 09:22:00

Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 11.MAR.2022 09:22:26

Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 11.MAR.2022 09:22:48

Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 11.MAR.2022 09:23:14

Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 11.MAR.2022 09:23:39

Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 11.MAR.2022 09:24:00

Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 11.MAR.2022 09:24:25

Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 11.MAR.2022 09:25:01

Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 11.MAR.2022 09:25:32

Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 11.MAR.2022 09:26:13


Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 11.MAR.2022 09:26:41




Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 11.MAR.2022 10:13:28

Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 11.MAR.2022 10:37:50

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 11.MAR.2022 10:14:07

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 11.MAR.2022 10:14:32

Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 11.MAR.2022 10:14:52

Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 11.MAR.2022 10:15:11

Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 11.MAR.2022 10:15:30

Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 11.MAR.2022 10:15:49

Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 11.MAR.2022 10:16:11

Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 11.MAR.2022 10:16:36

Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 11.MAR.2022 10:17:01

Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 11.MAR.2022 10:17:22

Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 11.MAR.2022 10:17:58

Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 11.MAR.2022 10:18:19

Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 11.MAR.2022 10:18:48

Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 11.MAR.2022 10:19:25