



Please refer to following plots:




Date: 2.DEC.2021 10:27:45




Date: 2.DEC.2021 10:28:02

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.DEC.2021 10:28:29

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.DEC.2021 10:28:55

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.DEC.2021 10:29:13

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.DEC.2021 10:29:30

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.DEC.2021 10:29:50

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.DEC.2021 10:30:10

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.DEC.2021 10:30:28

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.DEC.2021 10:30:45

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.DEC.2021 10:31:02

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.DEC.2021 10:31:19

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.DEC.2021 10:31:40

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.DEC.2021 10:31:59

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.DEC.2021 10:32:18


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.DEC.2021 10:32:37




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.DEC.2021 10:33:02

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.DEC.2021 10:33:26

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.DEC.2021 10:33:50

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.DEC.2021 10:34:13

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.DEC.2021 10:34:38

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.DEC.2021 10:35:02

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 2.DEC.2021 10:35:26

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 2.DEC.2021 10:35:49

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.DEC.2021 10:36:11

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.DEC.2021 10:36:28

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.DEC.2021 10:36:48

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.DEC.2021 10:37:05

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.DEC.2021 10:37:23

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.DEC.2021 10:37:40

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 2.DEC.2021 10:37:57


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 2.DEC.2021 10:38:14




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.DEC.2021 10:38:32

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.DEC.2021 10:38:52

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.DEC.2021 10:39:10

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.DEC.2021 10:39:26

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.DEC.2021 10:39:50

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.DEC.2021 10:40:09

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.DEC.2021 10:40:29

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.DEC.2021 10:40:48

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.DEC.2021 10:41:12

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.DEC.2021 10:41:36

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.DEC.2021 10:42:00

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.DEC.2021 10:42:23

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.DEC.2021 10:42:48

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.DEC.2021 10:43:12

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.DEC.2021 10:43:36


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.DEC.2021 10:43:59




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 17.DEC.2021 10:10:03

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 17.DEC.2021 10:14:19

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 17.DEC.2021 10:11:50

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 17.DEC.2021 10:13:20

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.DEC.2021 10:45:40

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.DEC.2021 10:46:00

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.DEC.2021 10:46:20

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.DEC.2021 10:46:37

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 17.DEC.2021 10:16:40

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 17.DEC.2021 10:19:18

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 17.DEC.2021 10:17:50

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 17.DEC.2021 10:18:36

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.DEC.2021 10:48:22

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.DEC.2021 10:48:41

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.DEC.2021 10:49:01


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.DEC.2021 10:49:23




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.DEC.2021 10:49:48

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.DEC.2021 10:50:05

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.DEC.2021 10:50:22

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.DEC.2021 10:50:39

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.DEC.2021 10:50:59

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.DEC.2021 10:51:18

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.DEC.2021 10:51:38

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.DEC.2021 10:52:00

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.DEC.2021 10:52:25

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.DEC.2021 10:52:49

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.DEC.2021 10:53:13

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.DEC.2021 10:53:36

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.DEC.2021 10:54:07

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.DEC.2021 10:54:34

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.DEC.2021 10:54:58


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.DEC.2021 10:55:21




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.DEC.2021 13:00:12

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.DEC.2021 13:00:35

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.DEC.2021 13:01:08

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.DEC.2021 13:01:37

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 16.DEC.2021 23:16:14

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 16.DEC.2021 23:17:21

Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 16.DEC.2021 23:18:55

Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 16.DEC.2021 23:20:14

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.DEC.2021 13:03:42

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.DEC.2021 13:04:08

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.DEC.2021 13:04:35

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.DEC.2021 13:05:05

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.DEC.2021 13:05:39

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.DEC.2021 13:06:06

### Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.DEC.2021 13:06:36


### Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.DEC.2021 13:07:03




Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 1.DEC.2021 17:41:32

Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 1.DEC.2021 17:41:46

Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 1.DEC.2021 17:42:00

Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 1.DEC.2021 17:42:17

Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 1.DEC.2021 17:42:37

Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 1.DEC.2021 17:42:55

Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 1.DEC.2021 17:43:14

Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 1.DEC.2021 17:43:35

Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 1.DEC.2021 17:43:57

Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 1.DEC.2021 17:44:23

Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 1.DEC.2021 17:44:44

Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 1.DEC.2021 17:45:08

Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 1.DEC.2021 17:45:36

Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 1.DEC.2021 17:46:05

Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 1.DEC.2021 17:46:33


Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 1.DEC.2021 17:47:02




### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.DEC.2021 10:55:46

### Band 66\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.DEC.2021 10:56:06

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.DEC.2021 10:56:24

### Band 66\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.DEC.2021 10:56:44

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.DEC.2021 10:57:02

### Band 66\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.DEC.2021 10:57:19

### Band 66\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.DEC.2021 10:57:36

### Band 66\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.DEC.2021 10:57:56

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.DEC.2021 10:58:17

### Band 66\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.DEC.2021 10:58:37

### Band 66\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.DEC.2021 10:58:54

### Band 66\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.DEC.2021 10:59:14

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.DEC.2021 10:59:35

### Band 66\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.DEC.2021 10:59:54

### Band 66\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.DEC.2021 11:00:13


### Band 66\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.DEC.2021 11:00:32




### Band 66\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.DEC.2021 11:00:57

### Band 66\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.DEC.2021 11:01:21

### Band 66\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.DEC.2021 11:01:56

### Band 66\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.DEC.2021 11:02:20

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.DEC.2021 11:02:45

### Band 66\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.DEC.2021 11:03:08

### Band 66\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.DEC.2021 11:03:32

### Band 66\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.DEC.2021 11:03:56