



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 25.NOV.2021 22:45:35

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 25.NOV.2021 22:45:53

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 25.NOV.2021 22:46:07

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 25.NOV.2021 22:46:21

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 25.NOV.2021 22:46:46

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 25.NOV.2021 22:47:00

Band 2_3 MHz_High_QPSK_RB15#0




Date: 25.NOV.2021 22:47:14

Band 2_3 MHz_High_16QAM_RB15#0




Date: 25.NOV.2021 22:47:31

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 25.NOV.2021 23:45:27

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 25.NOV.2021 23:46:31

Band 2_5 MHz_High_QPSK_RB25#0




Date: 25.NOV.2021 23:47:24

Band 2_5 MHz_High_16QAM_RB25#0




Date: 25.NOV.2021 23:48:14

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 25.NOV.2021 22:49:20

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 25.NOV.2021 22:49:42

Band 2_10 MHz_High_QPSK_RB50#0




Date: 25.NOV.2021 22:50:10

Band 2_10 MHz_High_16QAM_RB50#0




Date: 25.NOV.2021 22:50:35

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 25.NOV.2021 23:50:41

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 25.NOV.2021 22:51:42

Band 2_15 MHz_High_QPSK_RB75#0




Date: 25.NOV.2021 22:52:06

Band 2_15 MHz_High_16QAM_RB75#0




Date: 25.NOV.2021 22:52:40

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 25.NOV.2021 22:53:20

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 25.NOV.2021 22:53:47

Band 2_20 MHz_High_QPSK_RB100#0




Date: 25.NOV.2021 22:54:18

Band 2_20 MHz_High_16QAM_RB100#0




Date: 25.NOV.2021 22:54:44

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 25.NOV.2021 23:54:44

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 25.NOV.2021 23:55:14

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 25.NOV.2021 23:58:38

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 25.NOV.2021 23:59:24

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 26.NOV.2021 00:00:56

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 26.NOV.2021 00:01:22

Band 5_3 MHz_High_QPSK_RB15#0




Date: 26.NOV.2021 00:02:22

Band 5_3 MHz_High_16QAM_RB15#0




Date: 26.NOV.2021 00:03:00

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 26.NOV.2021 00:04:26

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 26.NOV.2021 00:05:01

Band 5_5 MHz_High_QPSK_RB25#0




Date: 26.NOV.2021 00:06:08

Band 5_5 MHz_High_16QAM_RB25#0




Date: 26.NOV.2021 00:06:59

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 26.NOV.2021 00:08:34

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 25.NOV.2021 22:59:13

Band 5_10 MHz_High_QPSK_RB50#0



Date: 25.NOV.2021 22:59:38

Band 5_10 MHz_High_16QAM_RB50#0



Date: 25.NOV.2021 22:59:57