



Please refer to following plots:




Date: 2.NOV.2022 10:06:27




Date: 2.NOV.2022 10:06:33

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 2.NOV.2022 10:06:40

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 2.NOV.2022 10:06:47

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 2.NOV.2022 10:06:55

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 2.NOV.2022 10:07:01

Band 2_3 MHz_High_QPSK_RB15#0




Date: 2.NOV.2022 10:07:08

Band 2_3 MHz_High_16QAM_RB15#0




Date: 2.NOV.2022 10:07:15

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 10:07:23

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 10:07:30

Band 2_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 10:07:37

Band 2_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 10:07:45

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 10:07:54

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 10:08:02

Band 2_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 10:08:10

Band 2_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 10:08:18

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 2.NOV.2022 10:08:27

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 2.NOV.2022 10:08:33

Band 2_15 MHz_High_QPSK_RB75#0




Date: 2.NOV.2022 10:08:41

Band 2_15 MHz_High_16QAM_RB75#0




Date: 2.NOV.2022 10:08:48

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 2.NOV.2022 10:08:57

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 2.NOV.2022 10:09:04

Band 2_20 MHz_High_QPSK_RB100#0




Date: 2.NOV.2022 10:09:12

Band 2_20 MHz_High_16QAM_RB100#0




Date: 2.NOV.2022 10:09:19

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 2.NOV.2022 10:09:28

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 2.NOV.2022 10:09:35

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 2.NOV.2022 10:09:42

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 2.NOV.2022 10:09:48

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 2.NOV.2022 10:09:56

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 2.NOV.2022 10:10:03

Band 4_3 MHz_High_QPSK_RB15#0




Date: 2.NOV.2022 10:10:10

Band 4_3 MHz_High_16QAM_RB15#0




Date: 2.NOV.2022 10:10:16

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 10:10:25

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 10:10:32

Band 4_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 10:10:39

Band 4_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 10:10:46

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 10:10:56

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 10:11:04

Band 4_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 10:11:11

Band 4_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 10:11:19

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 2.NOV.2022 10:11:27

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 2.NOV.2022 10:11:34

Band 4_15 MHz_High_QPSK_RB75#0




Date: 2.NOV.2022 10:11:42

Band 4_15 MHz_High_16QAM_RB75#0




Date: 2.NOV.2022 10:11:49

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 2.NOV.2022 10:11:58

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 2.NOV.2022 10:12:05

Band 4_20 MHz_High_QPSK_RB100#0




Date: 2.NOV.2022 10:12:12

Band 4_20 MHz_High_16QAM_RB100#0




Date: 2.NOV.2022 10:12:19

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 3.NOV.2022 08:40:24

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 3.NOV.2022 08:40:47

Band 7_5 MHz_High_QPSK_RB25#0




Date: 3.NOV.2022 08:41:46

Band 7_5 MHz_High_16QAM_RB25#0




Date: 3.NOV.2022 08:42:49

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 3.NOV.2022 08:43:33

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 3.NOV.2022 08:43:58

Band 7_10 MHz_High_QPSK_RB50#0




Date: 3.NOV.2022 08:45:03

Band 7_10 MHz_High_16QAM_RB50#0




Date: 3.NOV.2022 08:45:26

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 3.NOV.2022 08:46:58

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 3.NOV.2022 08:47:22

Band 7_15 MHz_High_QPSK_RB75#0




Date: 3.NOV.2022 08:47:54

Band 7_15 MHz_High_16QAM_RB75#0




Date: 3.NOV.2022 08:48:18

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 3.NOV.2022 08:49:32

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 3.NOV.2022 08:50:08

Band 7_20 MHz_High_QPSK_RB100#0




Date: 3.NOV.2022 08:50:44

Band 7_20 MHz_High_16QAM_RB100#0




Date: 3.NOV.2022 08:51:07

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 2.NOV.2022 11:32:00

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 2.NOV.2022 11:32:06

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 2.NOV.2022 11:32:13

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 2.NOV.2022 11:32:19

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 2.NOV.2022 11:32:27

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 2.NOV.2022 11:32:33

Band 5_3 MHz_High_QPSK_RB15#0




Date: 2.NOV.2022 11:32:41

Band 5_3 MHz_High_16QAM_RB15#0




Date: 2.NOV.2022 11:32:47

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 11:32:55

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 11:33:02

Band 5_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 11:33:09

Band 5_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 11:33:15

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 11:33:25

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 11:33:32

Band 5_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 11:33:41

Band 5_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 11:33:49

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 2.NOV.2022 11:33:58

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 2.NOV.2022 11:34:04

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 2.NOV.2022 11:34:11

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 2.NOV.2022 11:34:17

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 2.NOV.2022 11:34:26

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 2.NOV.2022 11:34:33

Band 12_3 MHz_High_QPSK_RB15#0




Date: 2.NOV.2022 11:34:39

Band 12_3 MHz_High_16QAM_RB15#0




Date: 2.NOV.2022 11:34:45

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 11:34:55

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 11:35:02

Band 12_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 11:35:09

Band 12_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 11:35:15

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 11:35:25

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 11:35:33

Band 12_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 11:35:41

Band 12_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 11:35:48

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 11:35:58

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 11:36:05

Band 17_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 11:36:12

Band 17_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 11:36:18

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 11:36:28

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 11:36:36

Band 17_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 11:36:44

Band 17_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 11:36:51

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 3.NOV.2022 08:56:12

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 3.NOV.2022 08:56:38

Band 38_5 MHz_High_QPSK_RB25#0




Date: 3.NOV.2022 08:57:37

Band 38_5 MHz_High_16QAM_RB25#0




Date: 3.NOV.2022 08:58:02

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 3.NOV.2022 08:59:19

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 3.NOV.2022 08:59:44

Band 38_10 MHz_High_QPSK_RB50#0




Date: 3.NOV.2022 09:00:20

Band 38_10 MHz_High_16QAM_RB50#0




Date: 3.NOV.2022 09:00:43

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 3.NOV.2022 09:01:54

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 3.NOV.2022 09:02:16

Band 38_15 MHz_High_QPSK_RB75#0




Date: 3.NOV.2022 09:02:46

Band 38_15 MHz_High_16QAM_RB75#0




Date: 3.NOV.2022 09:03:19

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 3.NOV.2022 09:04:10

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 3.NOV.2022 09:04:33

Band 38_20 MHz_High_QPSK_RB100#0




Date: 3.NOV.2022 09:05:35

Band 38_20 MHz_High_16QAM_RB100#0




Date: 3.NOV.2022 09:06:04

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 3.NOV.2022 13:22:25

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 3.NOV.2022 13:22:04

Band 41_5 MHz_High_QPSK_RB25#0




Date: 3.NOV.2022 13:21:24

Band 41_5 MHz_High_16QAM_RB25#0




Date: 3.NOV.2022 13:21:03

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 3.NOV.2022 13:23:25

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 3.NOV.2022 13:23:47

Band 41_10 MHz_High_QPSK_RB50#0




Date: 3.NOV.2022 13:24:24

Band 41_10 MHz_High_16QAM_RB50#0




Date: 3.NOV.2022 13:24:50

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 3.NOV.2022 13:25:40

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 3.NOV.2022 13:26:01

Band 41_15 MHz_High_QPSK_RB75#0




Date: 3.NOV.2022 13:26:45

Band 41_15 MHz_High_16QAM_RB75#0




Date: 3.NOV.2022 13:27:04

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 3.NOV.2022 13:28:13

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 3.NOV.2022 13:28:34

Band 41_20 MHz_High_QPSK_RB100#0




Date: 3.NOV.2022 13:29:08

Band 41_20 MHz_High_16QAM_RB100#0




Date: 3.NOV.2022 13:29:34

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 2.NOV.2022 11:37:02

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 2.NOV.2022 11:37:09

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 2.NOV.2022 11:37:16

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 2.NOV.2022 11:37:22

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 2.NOV.2022 11:37:31

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 2.NOV.2022 11:37:38

Band 66_3 MHz_High_QPSK_RB15#0




Date: 2.NOV.2022 11:37:45

Band 66_3 MHz_High_16QAM_RB15#0




Date: 2.NOV.2022 11:37:51

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 2.NOV.2022 11:38:01

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 2.NOV.2022 11:38:08

Band 66_5 MHz_High_QPSK_RB25#0




Date: 2.NOV.2022 11:38:16

Band 66_5 MHz_High_16QAM_RB25#0




Date: 2.NOV.2022 11:38:23

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 2.NOV.2022 11:38:33

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 2.NOV.2022 11:38:41

Band 66_10 MHz_High_QPSK_RB50#0




Date: 2.NOV.2022 11:38:50

Band 66_10 MHz_High_16QAM_RB50#0




Date: 2.NOV.2022 11:38:58

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 2.NOV.2022 11:39:07

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 2.NOV.2022 11:39:14

Band 66_15 MHz_High_QPSK_RB75#0




Date: 2.NOV.2022 11:39:22

Band 66_15 MHz_High_16QAM_RB75#0




Date: 2.NOV.2022 11:39:29

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 2.NOV.2022 11:39:38

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 2.NOV.2022 11:39:45

Band 66_20 MHz_High_QPSK_RB100#0



Date: 2.NOV.2022 11:39:53

Band 66_20 MHz_High_16QAM_RB100#0



Date: 2.NOV.2022 11:40:00