

C SAR Test Report No. :FA241205

Appendix D. SAR Test Setup Photos Head Exposure Condition



Right Cheek, Test Separation 0 mm



Right Tilted, Test Separation 0 mm



Left Cheek, Test Separation 0 mm



Left Tilted, Test Separation 0 mm

Body-worn Exposure Condition

Page D1 of D3



Front, Test Separation 15 mm



Back, Test Separation 15 mm

Sporton International Inc. (Kunshan)

TEL: 86-512-57900158 / FAX: 86-512-57900958

FCC ID: 2AJOTTA-1496

Issued Date : Jul. 05, 2022 Form version. : 200414

Report No.: FA241205

EUT Constructional Details with Back view



Left earphone



Right earphone

Couple of earphone


Note: The actual setups of left/right/couple of earphones during the testing were same as each position above three exposure conditions. Due to The phone has a back case with a box for putting in the earphones. When the back cover is sliding, during the test, it is slid on the back cover. The earphone is hidden inside and cannot be seen. Therefore, when shooting alone, the sliding cover is slid down and the actual internal earphone structure is seen. So we used plane presentation as instead.

TEL: 86-512-57900158 / FAX: 86-512-57900958

Issued Date: Jul. 05, 2022 FCC ID: 2AJOTTA-1496 Page D2 of D3 Form version. : 200414

Report No. :FA241205

Antenna Location



TEL: 86-512-57900158 / FAX: 86-512-57900958

Issued Date: Jul. 05, 2022 FCC ID: 2AJOTTA-1496 Page D3 of D3 Form version. : 200414