

Shantou Helicute Model Aircraft Industrial Co.,Ltd
Jiangbei Road, Longtian, Guangyi Street, Chenghai District, Chenghai,
ShantouCity, Guangdong, Shantou, China

Jul.10, 2023

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID : 2AKPPHLTH857W

Model Number: H857HW, DRC-445, DRC-447, DRCLS16, DRC-250, DRC-251, H850, H850-1, LS233691, LS233852, H848, H05NL, H05NCL, H07NL, H07NCL, H09NL, H09NCL, M801R, M803R, H805, H805W, H806, H806W, H809HW, H809SW, H811C, H811W, H812R, S812, H815HW, H815SC, H815SW, H816H, H816HC, H816HW, H817, H817C, H817W, H817H, H817HC, H817HW, H818H, H818HW, H818HC, H818HP, H818HPC, H818HPW, H819, H819HW, H820H, H820HC, H820HW, H821H, H821HC, H821HW, H822HW, H823, H823W, H823H, H823HW, H802G, H802W, H02G, H01C, H825, H825G, H825W, H826H, H826HW, H826HP, H826HPW, H827H, H827HW, H827S, H827SC, H827SW, H828H, H828HC, H828HW, H829, H830, H831H, H832, H833, H835, H836, H837, H838, H839, H850H, H851, H851SW, H851SPW, H852HW, H852HPW, H853H, H855HW, H856HW, H857HPW, H858, H859H, H859HPW, H859HW, H860H, H860HW, H860SW, H860SPW, H861G, H862, H863HW, H865SW, H865SPW, H865SPW-Pro, H866HW, H866HPW, H867, H868, H869SW, H869SPW, H869SPW-Pro, H870SW, H870SPW, H871HW, H872SPW, H873, S90, NH525, 56814, NH530, LS233009, LSB01, LS233837, LS233856, LS233857, LS233854, LS233855, SKU56814, SKU59537, NH425, NH430, S80, S400, S450, S70, S350, S500, DRC445-DOC, DRC445KIT-NOC, DRC447-DOC, DRC250-DOC, DRC251-DOC, DRC090-BLK, DRC090-SIL, DRCLSX10-DOC, H859, H863

To Whom It May Concern:

We, The Shantou Helicute Model Aircraft Industrial Co., Ltd hereby declare that the models are identical except the appearance color.

Except for the different above, no other modification is performed.

Sincerely,

Signature:

David Zhuang

Contact person: David Zhuang