




11A\_Ant1\_5745




11A\_Ant1\_5785




11A\_Ant1\_5825



11N20SISO\_Ant1\_5180







11N20SISO\_Ant1\_5220




11N20SISO\_Ant1\_5240








11N20SISO\_Ant1\_5500







11N20SISO\_Ant1\_5580




11N20SISO\_Ant1\_5700








11N40SISO\_Ant1\_5190




11N40SISO\_Ant1\_5230




11N40SISO\_Ant1\_5270







11N40SISO\_Ant1\_5310




11N40SISO\_Ant1\_5510




11N40SISO\_Ant1\_5550



11N40SISO\_Ant1\_5670




11N40SISO\_Ant1\_5755




11N40SISO\_Ant1\_5795









11AC20SISO\_Ant1\_5180




11AC20SISO\_Ant1\_5220




11AC20SISO\_Ant1\_5240











11AC20SISO\_Ant1\_5500




11AC20SISO\_Ant1\_5580




11AC20SISO\_Ant1\_5700











11AC40SISO\_Ant1\_5190




11AC40SISO\_Ant1\_5230




11AC40SISO\_Ant1\_5270









11AC40SISO\_Ant1\_5670




11AC40SISO\_Ant1\_5755




11AC40SISO\_Ant1\_5795



11AC80SISO\_Ant1\_5210




11AC80SISO\_Ant1\_5290




11AC80SISO\_Ant1\_5530





11AC80SISO\_Ant1\_5610



11AC80SISO\_Ant1\_5775

-----End of the report-----