

Ansjer Electronics Co., Ltd
301,1st Building,No.21 Yongtian Road, Xiangzhou,Zhuhai, Guangdong, China

Oct. 20, 2022

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID: 2ANTC-ZNC2892J

Models: ZNC2892J, C289W4GAG, C289W5FAG, C611W5FAG, C289W5GAF, C289W5GAG, C302W5GAG, C296W6SCG, C290W6SCG, C296W8SD1, C306 PRO, C1 PRO, C190W6HGF, C518W9SCG, C518W6SCG, C220W9SCG, C220W6SCG, C183W9SCG, C183W6SCG, ZNC2892L, ZNC2893Y, ZNC6113Y, ZNC2893Q, ZG2893M, ZG3023M, ZNC2965Y, ZNC2905Y, ZNC2968Y, ZNC3063Y, ZNC6963Y, ZNC1905S, ZND5184Y, ZND5185Y, ZNC2204Y, ZNC2205Y, ZNC1834Y, ZNC1835Y

To Whom It May Concern:

We, The Ansjer Electronics Co., Ltd hereby declare that the model : ZNC2892J is identical with the model : C289W4GAG, C289W5FAG, C611W5FAG, C289W5GAF, C289W5GAG, C302W5GAG, C296W6SCG, C290W6SCG, C296W8SD1, C306 PRO, C1 PRO, C190W6HGF, C518W9SCG, C518W6SCG, C220W9SCG, C220W6SCG, C183W9SCG, C183W6SCG, ZNC2892L, ZNC2893Y, ZNC6113Y, ZNC2893Q, ZG2893M, ZG3023M, ZNC2965Y, ZNC2905Y, ZNC2968Y, ZNC3063Y, ZNC6963Y, ZNC1905S, ZND5184Y, ZND5185Y, ZNC2204Y, ZNC2205Y, ZNC1834Y, ZNC1835Y, except the model name.

Except for the different above, no other modification is performed.

Sincerely,

Ansjer Electronics Co., Ltd
301,1st Building,No.21 Yongtian Road, Xiangzhou,Zhuhai, Guangdong, China

Ansjer Electronics Co., Ltd
Signature:

Lanner Lan

[Lanner Lan, General Manager]