


**Test Setup Photographs for the Smart Torque Tools**


**1. Radiated Emissions**

1.1. Configuration 1: Measurement up to 1 GHz

**Photo 1**




**Photo 2**




**Radiated Emissions (continued)**

1.2. Configuration 1: Measurement above 1 GHz

**Photo 3**



**Photo 4**



**Conducted Measurement**

**Photo 5**

