

Thundercomm Technology Co., Ltd  
Address: Building 4, No. 99, Data Valley Middle Road, Xiantao District, Yubei  
District Chongqing, China  
Tel: +86 010-82036511  
Fax: +86 010-82036511  
Email: Zhouqy0710@thundersoft.com

Date: 2021-12-28

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division


7435 Oakland Mills Road  
Columbia, MD 21046

Dear Sir/Madam,

We, Thundercomm Technology Co., Ltd hereby authorize Shenzhen Accurate  
Technology Co., Ltd. to act as a laboratory for testing and test report generation for  
the following project(s):

(Product name: TurboX-845; Model number: TurboX-C845-SOM;  
FCC ID: 2AOHHTURBOXC845SOM).

We affirm that the IPEX antenna port as shown in the red box picture below, installed  
in our product, but for marketing purpose, two IPEX antenna port was disabled to use by  
manufacture in the software, the end user has no capability to activate it.



Sincerely,

Signature: Qiyong Zhou

Qiyong Zhou

Manager