



# Appendix I

**External Photographs** 

### Top View of EUT- TT600-LM0Q-GL



## Bottom View of EUT- TT600-LM0Q-GL



# Left View of EUT- TT600-LM0Q-GL




Right View of EUT-TT600-LM0Q-GL




Page 3 of 13 UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

## Front View of EUT-TT600-LM0Q-GL



Back View of EUT- TT600-LM0Q-GL




#### Page 4 of 13

### Top View of EUT- TT601-LM0Q-GL



#### Page 5 of 13

Bottom View of EUT- TT601-LM0Q-GL



#### Page 6 of 13


#### Left View of EUT- TT601-LM0Q-GL






#### Page 7 of 13

#### Right View of EUT-TT601-LM0Q-GL




#### Page 8 of 13

#### Front View of EUT-TT601-LM0Q-GL



#### Page 9 of 13

### Back View of EUT- TT601-LM0Q-GL




Page 10 of 13

## Top View of EUT- TT603-LM0Q-GL




Bottom View of EUT- TT603-LM0Q-GL




# Left View of EUT- TT603-LM0Q-GL




# Right View of EUT-TT603-LM0Q-GL



## Front View of EUT-TT603-LM0Q-GL



Back View of EUT- TT603-LM0Q-GL



Page 13 of 13 UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.