


Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 1 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 2 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 3 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 4 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 5 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 6 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 7 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 8 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 9 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 10 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 11 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 12 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 13 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 14 of 16




Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 15 of 16





Internal Photos of EUT

Report No.: CN22IMYY 001

Model No. : ZNXDJQR01ZM

Page: 16 of 16



--THE END--