## **1. EXTERIOR PHOTOGRAPHS**







Fig.2

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 1 of 7



Fig.3



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 2 of 7





Fig.5



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 3 of 7 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.





Fig.7



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 4 of 7 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.



Fig.9



Fig.10

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 5 of 7

FCC ID:2APN5RM433

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig.11



Fig.12

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 6 of 7 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID:2APN5RM433




Fig.13

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 7 of 7