

Federal Communications Commission 7435 Oakland Mills Road
Columbia, Maryland 21046 USA


Date: 17-March-2021

Ref: DSS Mode for FCC ID: 2AR2O-VOB-P3310

Dear Examiner,

Our device does not use the DSS (Bluetooth) mode supported by the module. The device runs embedded software with Bluetooth disabled and does not provide any way for the user to access the operating system thus the user has no way of enabling this function.

Sincerely,
Stuart Wolf

By: Stuart Wolf 
Title: CTO
On behalf of: Augmedics LTD
Telephone: 972-54-8189993
Fax: 043730801
e-mail: stuart@augmedics.com